0
000
_
5
2
<u> </u>
3
3.1
7

FORM NO. 985-A	HC MEller Company (TVT)

Stock No. 26273 DOCUMENT NUMBER 145205

County of	·····FORES1	_	J
I	······································		., do hereby
certify that	on the	-23rd	day
ofJul	······	, 19	91 -, I found
evidence of	theQuart	@f	
	Sections 4		
•	36 East/Fo		
	i hereon; and	•	
	ed a new mo		
	d hereon to		•
location of			
	•		
Resident w	itnesses:		
	N.Spiess		·
	IXC.WWW		
	J. Spiess		
	-·		
		- -	
	-	·	
	36N	R 14E	
	1	•	
	1) j	1
,	'	; 	'
 	<u> </u>	· 	
	1	1	} •
Ì	1	1 1	· [
1/4	\ 	' 	'
		!	<u> </u>
T		! I	l 1
	ւ 	1	1
	l		• •
	-	·¦ — — —	
}	· •	, ,	

State of Wisconsin

CERTIFIED	LAND	CORNER	RESTORATION
U.S. PUE	BLIC	LAND	SURVEY

Index No.C -21

T36N R14E

History of original corner establishment:

Original comer established by James McBride, Gov't Deputy Surveyor in 1859, from which 8" Cedar bears N20E, 18 lks. and 10" Spruce bears N60W, 17 lks.

Description of corner evidence found:

Re-established Quarter Section Comer on a proportionate measurement to the G.LO. Survey of 1859.

Total distance from the Southwest Section Comer to the Northwest Section Comer of Section 1 is 5396.11'.

Set Quarter Section Comer 2704.14' of Southwest Section Comer and 2691.97' of Northwest Section Comer on a straight line between the two.

Description of monument and accessories I established to perpetuate the original location of this corner.


Set a 2-1/4" Forest County Aluminum pipe with 3-1/4" alloy cap.

Marked N.B.T.	's:						
Cedar 5"	S40E	16.58'		1/4	S2	S1	
Cedar 8"	S28W	29.30'	•				
Cedar 10"	N89W	32.03'					
Cedar 8	N2E	26.61'			19	91	
		•			S10	682	
				F	OREST	COUNTY	1

Dated at	Rhinelander /	, Wis., this	12th	day of	December	
	(Country Surveyor, Re					
•	(County Surveyor, Re	egistered Land Surveyor,	or other duly	authorized of	ficial)	
Office of R	egister of Deeds, County	of House	·····		, I hereby ce	rtify that the within
instrument	egister of Deeds, County was filed in this office for	or record on the	13±1	day o	s August	, 19. 92
at 9:30	o'clock M.					
	Jan Sale	Kenner				
	(Register of	Deeds)	•			
_			Dooutes			

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as proviously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

- {f} Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



GLEN
BARKER
S-1682
CRANDON
WI

Affix LanduSurveyor Scal

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Sidesture Baile

12/12/92 Dato

, -t₂-12⁻⁴