SS.

State of Wisconsin

CERTIFIED LAND CORNER RESTORATION

County of Forest	•		
I found evidence of the Westernship 36 North	est 1 Range 15 ace I established a n	East Four	day of July 1981, Section II th Principal Meridian, as described essories as described hereon to per-
Description of original monument Surveyed in 1859 by James Mc 40.00 chains north between and Section 11, set wood postamarac, 10", S46E, 82 lks. Tamarac, 10", S5W, 217 lks. 231, 3.50 chains south leave bears E & W 174.9, 2.65 north stream 20 19.50 north leave swamp bear	cBride Section 10 st , 54.12 feet , 143.22 feet e Alder swamp	Surveyed in 1968 Found 2" iron pipe Cedar post, which scribed. 190 feet	s: by Cochrane and Resvick alongside of 4" squared is very old. Post is t north from post to stream. edge of swamp from post.
Description of corner evidence for Found post and pipe. N62E, 13" Cedar blazed, scribown and badly decayed Tamaz growing out of stump. Swamp the original corner and month	ibed and location rack. Tree 10" p and creek call	- 14" D.B.H., S5W,	143 feet. 6" Cedar now
Description of monument and acceptaced a 2" x 60" aluminum p T36N, R15E, S10, \frac{1}{4}, S11, 198 From which the following bea B. Ash, 6", N52E, 40.88 feet Silver Maple, 16", N70W, 99. Set steel sign post, south, Creek 15 feet west of Silver Corner lies in Tag Alder swa	pipe alongside of 31, RLS-1558 ar: 03 feet 1.3 feet r Maple, runs NN	f post and iron pip	pe stamped as follows: MILO E STEFAN S-1558
	I.	OCUMENT NO. 124203	RHINELANDER, WIS.
Section 11 - Corner monument restored - 36 North - Page	(County Surveyors Registrated Office of Registrated I hereby certify the on the 13th No.	Stefan or, Registered Land Survey tion No. RLS-1558 ster of Deeds at the within instrument day of September Page No.	County of Forest It was filed in this office for record 19.83, and was filed in Book
Township30 North, Range	e <u>15 Hast</u>	Section, Inde	x No

43615102000

5
S C

O.O. 1	index No
State of Wisconsin } ss.	History of original corner establishment:
County of Forest	Original Government Survey in 1859 by James McBride, deputy surveyor. North between
	Sections 10 and 11 at 40.00 chains, set Quarter Section post from which the following bear:
I Gary L. Pisoni do hereby	Tamarack 10" S 46°E 82 lks; Tamarack 10" S 05°W 217 lks
certify that on the 13th day	· · · · · · · · · · · · · · · · · · ·
of May 19.94 I found	In 1968, Resvick and Bill Cochrane RLS U.S.F.S. found a 2" iron pipe along side a 4" scribed
evidence of the East quarter	squared cedar post which was very old. On 7/23/81, Milo Stefan RLS recovered the post and
corner of Section 10	pipe as described above and replaced pipe with a 2"x60" aluminum capped pipe monument from
Township36	which the following bear: Black Ash 6" N 52 E 40.88 feet
15 East Fourth Principal Meridian,	Silver Maple 16" N 70 W 99.03 feet
as described hereon; and that from this evidence	Description of corner evidence found: Steel sign post South 1.3 feet Cedar 13" N 62 E 37.8 feet
I established a new monument and accessories	Found the monument and bearing trees as described above:
as described hereon to perpetuate the original	Cedar 15" N 62°E 37.8 feet
location of this corner.	Black Ash 8" N 52°E 40.88 feet
•	O
Resident witnesses:	
	Steel sign post South 1.3 feet
	· ·
	•
	Description of monument and accessories I established to perpetuate the original location of this corner.
	Blazed and scribed the following new bearing tree: (Measurement taken to a nail
	in side of tree) Cedar 9" S 74 ⁰ E 62.05 feet
	Cedal 3 14 E 02.03 leec
	•
SECTION 10	Then Disease MT
	Dated at Iron River, MI , W. this 13th day of May 19. 95
	$\int_{0}^{\infty} \int_{0}^{\infty} \int_{0}^{\infty} dx dx = \int_{0}^{\infty} \int_{0}^$
	Signature Sary J. Former Title Land Surveyor Registration No. S-1634 (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Office of Register of Deeds, County of Joseph Market Inc.
	instrument was filed in this office for record on the 20th day of Malch. 1927
l i i	at <u>/ 30</u> o'clock M.

<u> </u>	(Register of Deeds)
	Du Sial Langueson Duni
Corner monument restored.	byDeputy

pescribe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(r) was the corner restored through acceptance of (1) an oblicerated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(gkh) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

