lo. 26273	UMBER 8148
Stock N	UMENT N
	D00

110	DI IQI IC	LAND	CHOVEY	MONUMENT	DECODO
U. J.	PUDLIC	LANU	SURVEI	MUNUMEN	RECURD

U. 5.	PUBLIC LAND SURVEY I	MONUMENT	RECORD	Index No. N-13			
State of Wisconsin	History of original corner establis	hnient:					
County of Forest			T.I. Nowlin North be	tween Sections 21 and 22,			
I Gary L. Pisoni , do hereby certify that on the 4th day	at 80.00 chains, set Section the following bear;	_		•			
of March, 19.93, I found	Tamarack	12"	N63°W	30 lks.			
evidence of the Southeast Section	Tamarack	10"	N57°E	25 lks.			
Corner of Section 16 Township 37, North, Range 13 East, Fourth Principal Meridian,							
as described hereon; and that from this evidence	Description of corner evidence for	und:					
I established a new monument and accessories	No original corner evide:	No original corner evidence was recovered. No other evidence was recovered.					
as described hereon to perpetuate the original	I restored the corner position by double proportionate measurements between the						
location of this corner. Resident witnesses:		of Section 16	and the Southeast Sec	tion corner of Section 21			
***************************************				•			
	3 inches above the groun	set a 2½ inch on a surface, with From which the sen to a nail in 10" 5" 13" 10" st	diameter aluminum pip h an aluminum cap sta following new blazed n side of tree) N44 E S86 E S28 E S73 W N46 E	l location of this corner. e monument, 3 feet long, mped; T37N R13E, S15, S16, and scribed bearing trees 24.60 feet 19.43 feet 54.97 feet 27.67 feet 0.67 feet			
SECTION 16	Dated at Iron River, MI	, Weisex, this	22nd day of	April , 19 93			
	Signature Samue 4: 7 (County Surveyor,	Title Registered Land Survey	Land Surveyor yor, of other duly authorized offic	Registration No. S-1634			
	Office of Register of Deeds, Coun	ty of Hole	07	, I hereby certify that the withi			
	instrument was filed in this office at. 1.25o'clock		day of.				
	/Romietar	of Deeds) -	**************				
= Corner monument restored.	By Seal	LACE	Deputy				

Describe any material discrepancy between the location of the corner as restored or (e) reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or recstablished, and (2) to at least 2 or the witness monuments shown on the drawing in (d), above.

See drawing below.

Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(gkh) Was the corner reestablished through lost corner proportionate mothods? If so, show the method, including the directions and distances to other public land survey corners used as

evidence or used for proportioning in determining the corner location? 10" Ash(NBT) Re-established through N44°E, 24.60 feet lost corner proportionate methods. Steel Sign Post, Secrion 210 212 Corner S21 S22 Ash(NBT) S86°E, 19.43 feet 10" Ash(NBT) s73°W, 27.67 feet Tamarack(NBT) S28°E, 54.97 feet S17 S16 GLO 40020 chs. GLO 40.20 ch S16 S15 GLO 40.20 chs. GLO 40.20 ch S15 S14 S20 S21 2589.75 2637.27 2614.06 2614.07 S21 S22 N 88⁰49'00"E N 88^O33'05"W 5227.02' 5228.13'

Gary L. Pisoni

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

PISONI

S-1634

IRON RIVER.