	R9-7150-11 (9/1/66) H. C. MILLER CO., MILWAUKEE 458624
CI	ERTIFIED LAND CORNER RESTORATION
State of Wisconsin  County of Forest	SS.
found evidence of the Southw Fownship 36 North	, do hereby certify that on the, day of _September, 1967, est Section corner of _Section 7, Range, Fourth Principal Meridian, as described nce I established a new monument and accessories as described hereon to permis corner:
Description of original monument Surveyed by Artemas Curtis North between Sections 13 a Set wood post.	· ·
Tamarack 12, S35°W, 36 lks Tamarack 10, N65°W, 20 lks Tamarack 8, N38°E, 40 lks Tamarack 10, S29°E, 10 lks	· •
Description of corner evidence fo	und:
Tamarack stump, bears N65 <sup>0</sup> 1	cedar post. W, 23.8 ft. from post found. W, 13.2 ft. from post found. E, 26.4 ft. from post found.
Replaced cedar post with a long, filled with concrete,	
R14E R15E S12 S7	from which the following blazed and scribed new bearing trees bear:
S13 S18 1967 S-802	Spruce, 6, N26°E, 68.07 feet or 103.14 lks. Tamarack, 7, S24°E, 100.73 feet or 152.62 lks.
	Resident witnesses.
	RHINELANDER,
	Dated at Rhinelander Wisconsin, Hiszoth day of Sentenber
Sec. 7	Signature Jean F. Resvick Title Cadas Signature (County Surveyor, Registered Land Surveyor, or other duly authorized official)  Surveyors Registration No. S-802
	Office of Register of Deeds County of Forest
	I hereby certify that the within instrument was filed in this office for record on the 31st day of January 19.69, and was filed in Boo
Corner monument restored	No. T Page No. J-1 of County Records.
	Signature Signature States of Deeds  ge 15 East , Section 7 , Index No. J-1 , Page No.
Township <sup>20 North</sup> , Rang	ge 15 Last, Section, Index No. J-1, Page No.

• •

U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
•••				1110110111	

Index	No	J-	25
	1 4 6 7 .		

State of Wisconsin				
1				
State of Wisconsin State				
I Gary L.Pisoni , do hereby certify that on the 22nd day of December , 19 93, I found evidence of the Northeast Section corner of Section 13  Township 36 , North, Range 14 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.				
Resident witnesses:				
•				
**** **********************************				
·				
······································				
SECTION 13				

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis.

North between Sections 13 and 18, at 80,00 chains, set Section corner wood post to Sections 12, 7, 13, 18, from which the following bear:

Tamarack	12"	s 35°W	36 links
Tamarack	10"	N 65°W	20 links
Tamarack	8"	и 38°E	40 links
Tamarack	10"	S 29 E	10 links

Description of corner evidence found:

In 1967, Jean Resvick, RLS with the U.S.F.S. restored the corner position at record bearing and distance from the original Tamarack bearing tree stumps. Set a 2 inch diameter galvanized iron pipe with a brass cap stamped as follows: T36N, R14E, R15E, S-12, S-7, S-13, S-18, 1967, S-802 from which the following new blazed and scribed bearing trees bear:

Spruce 6" N 26°E 68.07 feet Tamarack 7" S 24°E 100.73 feet

On 12/22/93, I found the above described monument but all bearing tree references were missing.

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new corner references: (Measurements taken to

nail in side of tree)

Tamarack 4"
N 63°E
17.66 feet

Tamarack 4"
S 69°E
29.48 feet

Tamarack 3"
S 86°W
13.94 feet

Tamarack 5" N 11 W 13.99 feet Steel sign post S 55 W 1.2 feet

Dated at Iron River, MI , this 23rd day of December 1993

Signature Aary L. Frank Title Land Surveyor Registration No. S-1634

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest Joseph Aary (ay of Joseph Aary)

at 130 o'clock M.

(Register of Deeds)

....Deputy


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below

(r) was the corner restored through acceptance or (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(gkh) was the corner reestablished through lost corner proportionate mothods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



S12 Section Corner **S13 S18** 

urveyor Scal! GARY LEE PISONI S-1634 IRON RIVER, Mi

Gary L. Pisoni

type or print name; certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

12-23-93

Signature