O = Corner monument restored.

FRTIFIFD	LAND	CORNER	RESTORATION
CKIIFICU	LAND	CORNER	RESTORATION

Index No.

History of original corner establishment:

Surveyed in 1865 by J.L. Nowlin
East corrected between sections 30 and 31
40.10 chains set 1/4 sectionspost
Birch, 10", N 72° E, 100 links
Cedar, 8", S 33° W, 150 links

The pipe was shown to me by the adjacent owners.



Description of corner evidence found:

Fence line North and South, Gravel road East and West. The R/W between the fences is 39 feet. At the mid point and in the road I found a 14" iron pipe. The top was bent from road grading. No original evidence was found. I accept this as the best available evidence of the corner position.

Description of monument and accessories I established to perpetuate the original location of this corner.

I replaced the pipe with a 1 inch inside diameter galvanized iron pipe, 30 inches long. (I left the other 1½" pipe alongside.) I set a 2½" Berntsen A-1 Federal Aluminum Monument, 30 inches long, North 17.0 feet of the corner with the cap stamped:

T37N, R13E, S30, S31, 1977, S-1107, REFERENCE CORNER, 17 FT
There were no other references available.

Dated at Hiles	, Wis., this 23 rd	day of	November	, 197.7
	Cockete Title Surveyor, Registered Land Surveyor, or other			
Office of Register of Deed instrument was filed in th	s, County of FOREST is office for record on the 29th	day of	November	y that the with
Lugent &	Stationist.		MBER 11	
By	(Register of Deeds) Dep	ut y		