REGISTER'S OFFICE \	Forest County, Wis. (, / A	Received for record this of day	of Lethuard A.D., 19 & / at	2.00.0'clock "P. M. and recorded,	in Vol. CORNER KESTORATION	page E-18 /	Land Hochardhanas	Register of Deeds
<u>Σ</u>	07070	5/707		-			MITY	

H.C. Miller Corposity Fry

OCUMENT NUMBER

115	PUBLIC	LAND	SHRVEY	MONUMENT	RECORE
U. J.	PUBLIC	LAND	SOUAFI	MICHARIEM	UECOU!

Stat County of	e of W	/isconsi umbia	n }	U.S.
I JAME certify th of 0 evidence corner of Township 12 Ea as describ I establis	S R. GR at on the ctober of the Section 38 st ed hereon bed a new	OTHMAN 231 With ons 5 & rand that monume n to perpe	d 19.86 ess Mea 8 Principal from this	do hereby day day I found nder h, Range Meridian, evidence ccessories
Resident Non	e .	•	•	:
	•			
· · · · · · · · · · · · · · · · · · ·		. 1		

	-

O = Corner monument restored.

History of original corner establishment: Original survey in 1859 by William E. Daugherty.

Dependent resurvey in 1937 by Wesson Cook. Set a concrete monument, 24 inches long, 6 inch diameter, 20 inches in the ground for a witness to the meander corner between sections 5 & 8 with brass cap marked:

WC ·	T38N S5 S8 R12E	from which	the	following bear:		
MC /	S8	Spruce Spruce		N28-1/4°E S30°E	47 1	
	1937	Spruce	5	530 E	42 1	.KS

J.F. Resvick in 1963 blazed & scribed the following bearing trees:

Index No.E-7-8.....

Description of corner evidence found:

Tamarack 3" S74°30'E 22.50' Tamarack 3" S13°30'E 43.65' Spruce 4" S23°W 17.90'

The following bearing trees:

Spruce	511	S23°W	17.90 fee
Tamarack	3''	S13°30'E	43.65 fee
Tamarack	4"	S74°30'E	22.50 fee

Description of monument and accessories I established to perpetuate the original location of this corner.

Corner position now falls in Woodbury Lake. Forest Service advised not to reset monument in Lake.

Dated at PORTAGE		<i>3</i> O	day of	OCTOBER	19.86
Signature mes & Store	Title	RC	5	Registrat	ion No. /32/
(County Surveyor, Reg	sistered Land Surveyo	or, or other duly	authorized officia	al)	
Office of Register of Deeds, County	of Fo	rest		, I hereby certi	fy that the within
(County Surveyor, Reg Office of Register of Deeds, County instrument was filed in this office for at 2:00 o'clock P. M.	record on the	24th	day of	February	
Faul Aschentien	ner				
(Register of I	De e ds)				
	-				

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Obliterated corner positon verified by existing bearing tree evidence.

(gkh) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location? - 1255.47' 05.47' **₽**8.58€ 2566.08 S 89° 38' 16"E, 1339.38 589°38'/6"E 89.11. NAIL IN 4" TAMARACK Affix Land Surveyor Scal JAMES R. NAIL IN 5" SPRUCE GROTHMAN S-1321 NAIL IN 3" TAMARACK PORTAGE WI JAMES R. GROTHMAN, Registered Land Surveyor No. 1321 (i) (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Syrvey Monument Record is correct and complete to the best of my Knowledge and belief. Signature Certificate ready for filing: District Kanger