State of Wisconsin } ss.	History of original corner establishment: Original Government Survey in 1858 by Alfred Millard. At 40.00 chains set Quarter Post, from which the following bear; Spruce, 12", N28 W, 25 lks., Yellow Birch, 10", S70 E, 10 lks.						
County of <u>Forest</u>							
I Gary L. Pisoni do hereby							
certify that on the 3rd day				•			•
of March 19.94, I found	In 1989, Glen Barker, RLS, with Consolidated Papers, restored the corner position at						
evidence of the South Quarter	proportionate and o						
corner of Section 33	Set a l" diameter a	_ <del>_</del>		<del>-</del>			azed and
Township	scribed the following new bearing brees:			Cedar 12" N82 E 6.22 feet			
as described hereon; and that from this evidence  Description of corner evidence				Cedar 9"	Ω	36.57 feet	
I established a new monument and accessories				Hemlock 11"	S64°W	18.67 feet	
as described hereon to perpetuate the original	Dans Janeans and	hooming two	റെ റെ റ്റേദ്യ	ihod aboute			
location of this corner.	Found monument and bearing trees as described above; W. Birch 11" N43 E 90.10 feet						
	Cedar	14"	N82°E	6.23 feet			
Resident witnesses:	Cedar	10"	S05°W	36.59 feet		÷	
	Hemlock	15"	s64°W	18.71 feet		•	
	r			•	-		
	-		•		•	•	
		•		•	•		
······································	Description of monumen	it and accessorie	s I established	i to perpetuate the or	iginal location	of this corner.	-
	Set a Steel Sign Po	ost	N64 <sup>O</sup> W	1.00 feet			_
•		•	•			•	•
						••	•
				•			
						• •	
	•			•		,	
							4
	•						
	1						
SECTION 33	Dated atTron Ri	iver, MI	,xXXixx, this	5th day of	March		, 19 <sup>95</sup>
						<u>.                                    </u>	a 1624
	Signature I Buy Till	Surveyor Register	red Land Surveyo	Land Surveyor or, or other duly authorize	d official)	Registration N	o <u>S-1634</u>
	Office of Register of Dee			1 January authoriza		-also consider tha	e dha wishin
	instrument was filed in t	<del>-</del>		1020 do	v of	reby certify tha	19 97
	at/i30 o'clock	) M.	.Oi O.I CI.C		y (1		
		······································				-	-
		(Register of Deed	s)				
Corner monument restored.	By	Salaur		Deputy		•	
		<del> </del>					

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.


None

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(gall) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No



10" Cedar 505<sup>0</sup>W, 36.59 feet

(i) i, Gary L. Pisoni
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Lang L. France 4-10-25

GARY LEE
PISONI
S-1634
IRON RIVER,
MI