. CE	RTIFIED LAND CORNER RESTORATION
State of Wisconsin	
State of Wisconsin County of Forest	, ▶■
•	
I found evidence of the <u>east of</u> Township 39 North	do hereby certify that on the 16th day of September, 19.74, uarter corner of Section 33. Range 13 East, Fourth Principal Meridian, as described
petuate the original location of this	nce I established a new monument and accessories as described hereon to per- is corner:
Description of original monument	and accessories and subsequent restorations:
Tamarack 10, S76E, 16 lks. Tamarack 10, N30W, 5 lks.	section 33 and 34 set post.
1.50 chains south, leave sw	amp E-W
	•
Description of corner evidence for	ınd:
3x3x3 post	
Tamarack snag with scribing Tamarack stump N30 ^O W, 5 lks	·
-	•
Description of monument and acc	essories I established to perpetuate the location of this corner:
	a 2 inch inside diameter galvanized pipe, 5 ft. long, filled cap stamped: T39N, R13E, 1/4, S33, S34, 1975, S-802
No BT's corner is in an ope	
	JEAN F.
, 1	JEAN F. JEAN F. RESVICK
	RKINELANDER, WIS.
	Resident witnesses
	Dated at Rhinelander Wisconsin, this 31 day of March
Sec. 33	1975 Signature Jean F. Resvick Title Land Surveyor
· · · · · · · · · · · · · · · · · · ·	(County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-802 DOCUMENT 107228
	Office of Register of Deeds County of Forest
Corner monument restored	I hereby certify that the within instrument was filed in this office for record on the 16th day of June 19.75, and was filed in Book
	No
	Signature La Allega La Transactitle Register of Deeds

Township 39 North, Range 13 East, Section 33, Index No. X-13, Page No.

Stock No. 2627

State	of	Wisconsi	in
ounty of	For	est	

I William B. Cochrane day of July 19 94 I found evidence of the East Quarter corner of Section 33 North, Range North, Range 13 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

*	! ! !	 	
	<u> </u>	!— — — - ! !	! !
-	SECTI	DN 33 _ =	
, 		 	
!		, [

= Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. X-13

History of original corner establishment:

Original Government Survey by William E. Daugherty in 1865.

At 40 chains North between stecions 33 and 34 set post from which the following bear; Tamarack 10" S76°E 16 1ks

Tamarack 10" S76°E 16 1ks
Tamarack 10" N30°W 5 1ks

In 1974 Jean Resvick and Milo Stefan found 3"X3" wood post, remains of Tamrack stump S76°E, 10.60 feet, rotted tamarack stump N30°W, 3.30 feet. Set a 2½"X60" galvanized iron pipe monument with brass cap stamped: T39N, R13E, 1/4, S33, S34, 1975, S-802.

No Bearing Trees were made at this time.

Description of corner evidence found:

Found the 1975 monument as discribed and in place.

Made the following bearing trees.

Tamarack	2"	N71°E	37.33 feet
Sprúce	3"	S16°W	41.47 feet
Steel sign	post	Southwest	.25 feet

Description of monument and accessories I established to perpetuate the original location of this corner.

Made the following bearing trees.

Tamarack	2"	N71°E	37.33 feet
Spruce	3"	S16°W	41.47 feet
Steel sign	post	Southwest	25 feet

Dated at	Hiles	, Wis., this	22 nd day of	December 19	994
Signature W	illiam B.	CochraneTitle	Land Surveyor	Registration No	<u>5–110</u>
•	(County Surv	veyor, Registered Land Surveyor	, or other duly authorized	d official)	
Office of Reg	ister of Deeds,	County of Hores	/-	y of	withi
instrument v	vas filed in this	office for record on the	23col da	y of August 1	9.2
at 230 0	clock	M.			
		•		•	

By Jan Tanelling Deput

(Register of Deeds)

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness. monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Found perpetuated corner location.

(gkh) was the corner reestablished through lost corner proportionate methods? It so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

> Tamarack 2" N71°E 37.33' Steel sign post Southwest .25' Spruce 3" WILLIAM B.
> COCHRANE
> S-1107
> HILES,
> WISCONSIN
>
> SURVEY
>
> S S16°W 41.47'

William B. Cochrane [i] (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Accord is correct and complete to the best of my knowledge and belief.

Signature