= Corner monument restored.

| 115  | PUBLIC | LAND | SURVEY | MONUMENT    | RECORD |
|------|--------|------|--------|-------------|--------|
| U.S. | PUBLIC | LAND | SOUATI | MOLACIAITMA | 11001  |

| Index | No  | R-19 |
|-------|-----|------|
| 11100 | 110 |      |

| State of Wisconsin  County of Forest  I. Gary L. Pisoni do hereby certify that on the 24th day of July 1991 I found evidence of the South Quarter corner of Section 23  Township 41 North, Range | History of original corner est<br>Original Government Subetween Sections 23 an<br>23 and 26, from which<br>Cedar<br>Spruce  | urvey in 1865<br>nd 26, at 40.   | 00 chs., set Qua  | Daugherty. West Corr<br>arter Section Post t<br>21 lks.<br>15 lks. | ected<br>o Sections             |
|--|---|--|---|--|---------------------------------|
| 14 East Fourth Principal Meridian, as described hereon; and that from this evidence  | Description of corner eviden  | ce found:  |   |  |                                 |
| I established a new monument and accessories   | No original corner evi  | idence was re  | covered.  |  |                                 |
| as described hereon to perpetuate the original location of this corner.  | I restored the corner<br>Meander Corner to the  | position at<br>East and the  | proportionate d<br>Southwest Sect   | istance and on line<br>ion Corner of Sectio                        | between the<br>n 23.            |
| Resident witnesses:  |   |  | *   |  |                                 |
|  |   |  |   |  |                                 |
|  | Description of monument ar At the corner position 3 inches above the gro 1991, S-1634. From wh (measurements taken to Cedar Ash Cedar Steel Sign Pos Monument is 12 feet Se | n, set a $2\frac{1}{2}$ iound, with arich the folice o a nail in some $7''$ $7''$ st | nch diameter al<br>n aluminum cap s<br>owing new blazed<br>side of tree)<br>S64 <sup>O</sup> E<br>S80 <sup>O</sup> W<br>N74 <sup>O</sup> W<br>South | uminum pipe monument<br>tamped; T41N R14E, 1                       | , 3 feet long,<br>/4, S23, S26, |
| SECTION 23   | Office of Register of Deeds, instrument was filed in this at 10:15 o'clock.   | Qoeru  | Title Land  | Surveyor   | Registration NoS-1634           |

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.


Survey requested by;

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(gkh) was the corner reestablished through lost corner proportionate mothods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Reestablished through lost corner proportionate methods.



Car

Date

District Ranger