CEDTICIED	LAND	CODMED	RESTORATION
CERTIFIED	LAND	CURINER	RESTURATION

History of original corner establishment:



Index No. № -13

Description of corner evidence found:

FOUND 13/4" IRON PIPE BELOW 16" x 5" x 9" STONE (COULD SEE NO DISTINCT MARKINGS ON STONE) IRON PIPE WAS 26" BELOW ROAD SURFACE. PIPE CHECKED GOOD WITH DISTANCE SHOWN ON M. HUTCHINSON'S NOTES (19.71 CH., SW CORNER SECTION 15 TO W'8 CORNER OF SW 14, SECTION 15)

SET 3/4" x 24" IRON ROD OVER FOUND IRON PIPE.

HGLADE

Description of monument and accessories I established to perpetuate the original location of this corner.

T32N RIE E 16 15 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	P K. IN POWER POLE OLD FENCE (DOWN)	N		
OLD FENCE (DOWN) RAGLADE T32N RIIE T32N R	O- 2" + 42" B I.P. W/ BRASS CAP			
Dated at ANTIGO , Wis., this	14 TH day of MAY	, 19. 79		
Signature Wolfe & Title REGISTERED LAND SURVEYOR Registration No. 1342 (County Surveyor, Registered Land Surveyor, or other duly authorized official)				
Office of Register of Deeds, County of	, I hereby certify	that the within		

(Register of Deeds)

.....Dep