CERTIFIED	LAND	CORNER	RESTORATION

Index No. J - /	
-----------------	--

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

4" iron pipe with brass cap.

Description of monument and accessories I established to perpetuate the original location of this corner.

∦ ev	r ET's				Chapt Count
811	Spruce	S17E	16:	10"	732NAIZE X
511	Spruce	S15W	13:	7"	145 -14
811	Spruce	S76W	9:	6"	9-25-39

Antigo Dated at		1 day of	April	19 78
Dated at	Hy Title Reg.	Lend Surveyor	Registration N	o. \$685
(County Surveyor, Register	ed Land Surveyor, or o	ther duly authorized offic	ial)	
Office of Register of Deeds, County of		***************************************	, I hereby certify tha	t the within
nstrument was filed in this office for rec	ord on the	day of		, 19
o'clock				
	······································			
(Register of Deeds				

State of Wisconsin

County of Langlade

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 19.78, I found evidence of the 1/4 corner of Section 11 & 14

Township 32, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

T32N R12E
Seethow 14
132N R12E
!!!!!
1 1

O = Corner monument restored.