


**LANGLADE COUNTY**

**U.S. Public Land Survey Monument Record**

TYPE OF MONUMENT: Existing 2" Iron Pipe  
 COUNTY COORDINATES: N 400961.55  
 WCCS NAD83(1991) E 696755.22  
 ELEVATION / DATUM: 1434.5± NAVD88  
 THETA ANGLE: (maintenance)  
 FIELD BOOK / REMARKS: Town of Langlade

CORNER NO. V-15  
 SECTION 27  
 TOWNSHIP 33N  
 RANGE 13E



LOCATION  
(Indicated by 'X')




**BASIS FOR MONUMENT LOCATION**

(Use reverse side if necessary)

Show info such as: History of corner, with reference to Vol. and Page, dates, surveyor; exact description of monument replaced; if location computed, by traverse or GPS; landowner remarks, etc.

I found, verified and accepted an existing 2" iron pipe, appearing undisturbed, as called for on a tiesheet by Wayne Dobbratz dated 6/07/1993. He reports that R.J. Poss, RLS S-1, replaced an old squared stake with this 2" iron pipe in 1971. I could not find Dobbratz's tie #4. The aluminum nails shown in the bearing trees have been buried by subsequent tree growth. I decided to set new auxiliary nails, rather than further damaging the trees by additional cutting to search for the old nails.

SEAL:



Y331327 0020 2016

CERTIFIED CORRECT:

*David L. Roberts*  
 Professional Land Surveyor

DATE: June 27, 2016

**TIE SKETCH** N.T.S.

(Show at least four ties)

Bearings shown are magnetic, rounded to the nearest degree. To reach the corner from the backyard of house #N7720, head south to the southern-most edge of lawn near the river. Then head southwesterly into the woods about 50 feet along a trail to the corner on the right, in brush, projecting up.

