
O = Corner monument restored.

CEDILLIED	LAND	CODNED	RESTORATION
L.F.R.I.I.F.I.F.I.J.	IANI	LURIVER	RESIDMATION

History of original corner establishment:



Description of corner evidence found:

Located Wit. Corner to a stone in road. Wit. Cor. had been hit by tree

Skidder and Knocked out of position. Excavated road and found

Stone with a triangular corner pointing W. Stone was tipped

on its side.

-NBT 12" OAK - + AT BASE Description of monument and accessories I established to perpetuate the original location of this corner. - NBT 6" NORWAY PINE ON EDGE OF PLANTATION - + AT BASE. SET 2" × 42" PIPE WITH BRASS CAP MONUMENT AT CORNER - 6" UNDER ROAD SURFACE. SET NEW WITNESS E TOWN LINE ROAD CORNER AND MARKED NEW BEARING TREES. ELCHO NOVEMBER 1975 ... Wis., this..... Signature Welleaus J. Helly Title Registered Land Surveyor Registration No. 5 1098 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of ................................, I hereby certify that the within at.....o'clock...... M. (Register of Deeds)