Document Number

REGISTER'S OFFICE
Forest County, Wis.

Received for record this day
of August A.D., 2002 at
8:45 o clock AM. and recorded
In Vol. Corner Restoration
page C.D-1

Register of Deeds

176286

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(As Required by W Adm. Code)

History of original corner establishment and subsequent restorations and descriptions of any record, monument, occupational, testimonial or other evidence considered:

- 1857 Alfred Millard, marked a 36" Dia. W. Pine for Meander Corner and made the following B.T.'s:
 W. Pine 18", N 39° E, 17 lks., 11.22 feet
 W. Pine, 14", S 70° W, 33 lks., 21.78 feet.
- 1946 The U.S. General Land Office performed a Dependent Resurvey of Section 6, T34N R14E.

 The meander corner was recovered in that survey and was mentioned as a rotted pine stump.

 A 6" dia. X 24" long concrete monument with a stamped brass cap was set at this location.

 The following new B.T.'s were made: Elm 6", N 62 1/2° E, 34 lks. 22.44 feet

 W. Pine 18", N 36 3/4° W, 122.5 lks, 80.85 feet
- 2002 I found the 6" dia. concrete monument mentioned above in excellent condition. Made the following new B.T.'s: Oak 13", S 32° W, 9.87 feet; Oak 9", N 18° W, 38.28 feet

 Oak 9", S 77° W, 61.17 feet; 2" Iron Pipe, N 02° E, 21.04 feet

Corner was: (Check All That Apply)

- Restored through acceptance of an obliterated evidence location.
- Restored through acceptance of a found perpetuated location.

 Considered a lost corner and reestablished through lost corner proportionate methods (include a plan view drawing showing distances and directions to other Public Land Survey Corners used for
- proportioning and determining the corner location).

 Restored or reestablished in a location that differs from a previous restoration or reestablishment (include a plan view drawing and indicate what was set and/or found).

Describe the monument and accessories used to perpetuate the location of this corner (include a plan view drawing and indicate what was set and/or found).

