		u _	ース
Index	No.		1

State	of	Wisco	onsin		}	
County of	Fo	rest	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	• • • • • • • • • • • • • • • • • • • •	. } ss.	
I Gary L.Pisoni , do hereby certify that on the 19th day of October ; 19.94 , I found evidence of the South One-Sixteenth corner of Sections 9 and 10. Township 36 , North, Range 15 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner. Resident witnesses:						
***************************************		e q				
		_				
		•				
	! 		<u>-</u> 			
	<u>:</u>	-	<u>-</u>			
	[!		i I	,		
	¦_S	ECT	10 N	_ 1	o	
	ī l		ı — — — 1			
	! 1		[1			
	<u> </u>		¦ – –		<u>-</u>	
	1] 			
	1 1		l 1			

Corner monument restored.

History of original corner establishment:

Corner was originally established by J. Melendy in 1911. He set a wood post marking the S 1/16 corner position. In 1985, Kim H. Pritzlaff found and 1 1/4" dia. iron pipe located in a rock cairn, said pipe was driven in an old post point. Kim Pritzlaff RLS accepted the iron pipe as the 1/16th corner and replaced it with a 2" dia. aluminum pipe monument.

Description of corner evidence found:

Found a 2" dia. aluminum pipe monument set by Kim H. Pritzlaff RLS. and found monument to be 4' out of position.

I re-established the S 1/16 corner position on line and at midpoint between the Southwest Section corner of Section 10 and the West Quarter corner of Section 10.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position, set a 1" dia. aluminum pipe monument, 3 feet long, 3 inches above the ground surface, with a 2" aluminum capped stamped: T36N, R15E, S 1/16, S-9, S-10, 1994, S-1634; from which the following new blazed and scribed bearing trees bear: (all measurements taken to a nail in side of tree)

Sugar Maple	5"		27 W	15.35	feet
Red Maple	6 "		83°E	43.64	feet
Sugar Maple	6"	_	52°E	23.60	feet
Steel sign pos	st		61°E	2.40	feet
Erroneous alum	mon.		76 ⁰ 55'35"E	4.07	feet
Steel sign pos	st	S	45 ⁰ W	0.88	feet

Dated at	Iron River, MI		day of	December	
	1 10		-		a 11.624
Signature	Vary L. Tason	Title Land Surv	eyor	Registra	ation No.S-1034
_	County Surveyor, Register	ered Land Surveyor, or other d	uly authorized of	fficial)	
Office of Reg	County Surveyor, Register of Deeds, County of was filed in this office for recorded. M.	Follot	<i>.</i> /	I hereby cer	tify that the within
instrument '	was filed in this office for re	cord on the	day o	Maich	
at / 30 c	clock M.				

	(Register of Deeds)	
· / /		
Ry all	Smillelle	Deputy

e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Found corner to be in error as described on front page.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Re-established on line and at midpoint between Section corner and Quarter corner.

(gkn) Was the corner reestablished through lost corner proportionate mothods? It so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

