सटस	07070
<u> </u>	•
H.C.Miller Company Miller Company Mi	_
C.Mille	4
Ì	Parent.
	- 4
	- 64

Index	No.	R-21	
111000			۰

County of Forest I Gary L. Pisoni do hereby certify that on the 21st day of August 19.91, I found evidence of the Southeast Section corner of Section 23 Township 41 North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original
certify that on the 21st day of August 1991, I found evidence of the Southeast Section corner of Section 23 Township 41, North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories
location of this corner.
Resident witnesses:
SECTION 23

History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty. North bet. Sections 25 and 26 at 80.00 chs. set Section Corner Post to Sections 23, 24, 25 and 26,

from which the following bear: Birch

45 1ks. 18 lks. Fir

Description of corner evidence found:

No original corner evidence was recovered.

I restored the corner position using proportionate distance and on line between the Meander Corner between Sections 23 and 26 located on the East Bank of the Brule River and the Southeast Section Corner of Section 24.

Description of monument and accessories I established to perpetuate the original location of this corner. At the corner position, set a $2\frac{1}{2}$ inch diameter aluminum pipe monument, 3 feet long, 3 inches above the ground, with an aluminum cap stamped; T41N R14E, S23, S24, S25, S26, 1991, S-1634. From which the following new blazed and scribed bearing trees bear; (measurements are taken to a nail in side of tree)

S. Maple	7''	N75 E	34.87 feet
S. Maple	5"	S33 ^O E	37.17 feet
R. Maple	811	s17 ⁰ W	15.43 feet
Hemlock	11''	$N44^{O}W$	34.06 feet
Steel Sign Po	st	s65 ⁰ W	0.70 feet

Dated at	Iron River, Ml	****\ this	16th	dav of	February	
	Hay I. Prome	Title	Land	Surveyor	Regis	stration NoS-1634
0.00	(County Surveyor, Register	ed Land Survey	or, or other	duly, authorized.c	# t t	
Office of Re	egister of Deeds, County of was filed in this office for rec	ord on the	XII)# day	of Raid	19.93
at.10:45	o'arack A M.	renner			V	
9	(Register of Deeds	s)				


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(9th) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location? Reestablished through lost corner proportionate methods.



Gary L. Pisoni

(i)

type or print name; certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

March 13th Yan Signature

Survey requested by; District Ranger Date

R.14E R.15E

S.24 | S.19

S.25 | S. 30