	26273	(C)
Mignather Wiccong	Š	658 658
•	ock	, <del>E</del>

## MONUMENT RECORD LAND SURVEY U.S. PUBLIC

Index	No	V-17	
HUUEA	1 M L J .	<b>.</b>	

State	of Wisco	nsin	<u>}</u>	
County of	Forest		} ss.	
I Gary L. Pisoni do hereby certify that on the 24th day of July 19.91, I found evidence of the Southwest Section corner of Section 26  Township 41 North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.				
Resident witt	nesses:			
**** **********************************		•	•	
		i i	1	
	-	• 1 •	! !	
		! !	<u>-</u>	
1	•	ľ I	! !	
1	SECTI	<u>ри 5е</u>	! !-	
	•	! !		
		1	1	
<del> </del>		' !	<u>-</u>	
	•	 [ 	1	
<u> </u>		- !		
Corner =	monunient	restored.	-	

History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty. North between Sections 34 and 35, at 80.00 chs., set Section Corner Post to Sections 26, 27, 34 and 35, from which the following bear;

N44<sup>O</sup>W 43 lks. Tamarack S80°E 15" 37 1ks. Tamarack

Description of corner evidence found:

No original corner evidence was recovered.

I restored the corner using double proportionate methods between Gaspardo Creek and the Meander Corner between Sections 22 and 23, and between the Southwest Section Corner of Section 27 and the Southeast Section Corner of Section 26.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position, set a  $2\frac{1}{2}$  inch diameter aluminum pipe monument, 3 feet long, 3 inches above the ground, with an aluminum cap stamped; T41N R14E, S26, S27, S34, \$35, 1991, S-1634. From which the following new blazed and scribed bearing trees bear; (measurements taken to a nail in side of tree)

		· · · · · · · · · · · · · · · · · · ·	
W. Spruce	9"	N39 <sup>O</sup> E	43.36 feet
Tamarack	10"	S10 <sup>O</sup> E	18.49 feet
Tamarack	12''	S33 <sup>O</sup> W	27.71 feet
W. Spruce	1411	N54 <sup>O</sup> W	9.63 feet
Steel Sign Post		East	0.53 feet

Dated at	<u>lron River, Ml</u>	,XXXX, this	<u> 16th</u>	day of	February	19.92
Signature	(County Surveyor, Register of Deeds, County of was filed in this office for	Title	Land Si	urveyor	Rcgis	tration NoS-1634
	(County Surveyor, Regis	stered Land Survey	yor, or other	duly authorized o	official)	
Office of R instrument	egister of Deeds, County of was filed in this office for a	record on the	1 10	day	of Thereby of	2. 19.93
at <i>/0:45</i> (	oclock A M	e dren	س			
	(Register of De	c <del>e</del> ds)				

By......Deputy


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as proviously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(gali) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location? Reestablished through lost corner proportionate methods.



correct and complete to the best of my knowledge and belief.

Survey requested by;

District Ranger