

EXIST. SECT. COR.
 ANGLE IRONS
 WELDED TOGETHER
 BRASS CAP SET.


MAGNETIC

Z

SECT. COR. T. 32N. - R. 10E.

SECTION 11

T. 32N. - R. 10E.



SECTION 14

T. 32N. - R. 10E.

MARKED WITH 2" BRASS CAP ON 2" BLACK PIPE 3'-6" LONG
 BRASS CAP SET ALONGSIDE EXISTING ANGLE IRONS WELDED TOGETHER
 AND USED AS CORNER MARKER.

12 17
13 18

MARKED WITH 2" BRASS CAP ON 2" BLACK PIPE 3'-6" LONG
 BRASS CAP SET ALONGSIDE EXISTING 2" x 3" STEEL PIPE USED AS CORNER MARKER.

11 12
14 13

BRASS CAP ON 2" x 3'-6" LONG BLACK PIPE.

12
13

1/4 SECT. CORNER - BRASS CAP ON 2" x 3'-6" LONG BLACK PIPE

12
13

WEST 1/16 CORNER } BRASS CAP ON 1 1/2" x 3'-6" LONG BLACK PIPE PAINTED ORANGE
 EAST 1/16 CORNER }

SECTION 12

T. 32N. - R. 10E.

W 1/16 Cor.

12

13

5444.65'

12

13

12

13

12

13

DRAWN BY: W. KELLY
 DATE: 20 MAY 1974
 SCALE: 1" = 600'

SECTION CORNER
 T. 32N. - R. 11E.

EXISTING SECT. COR.
 2" x 3" STEEL PIPE
 2" BRASS CAP SET.

2




William J. Kelly 21 May 1974

RECORD # 10024

LANGLADE COUNTY SURVEYORS OFFICE

DATE EN'D 6-1-93 RV. S.J.F.

Plat of Survey for G. Ritz of Route 2, Deerbrook, Wi.
to locate the West $\frac{1}{16}$ Corner on the South Section Line
of Section 12-T.32N.-R.10E. Original Section Corners
 $\frac{10\frac{1}{2}}{15}$ and $\frac{12\frac{1}{2}}{15}$ in T.32N.-R.10E., located from photo-
graphs and identified by local residents. Original
Survey Records indicate that distance was long between
Section Corner $\frac{10\frac{1}{2}}{15}$ and $\frac{12\frac{1}{2}}{15}$. Distance prorated
51% across the South Line of Section 11 and 49% across
the South Line of Section 12 in Original Records. Section
Corner $\frac{11\frac{1}{2}}{15}$ $\frac{1}{16}$ was re-established based on
the prorated percentage of Distance on Original Survey.
The West $\frac{1}{16}$ Corner, the $\frac{1}{4}$ Section Corner and the East $\frac{1}{16}$
Corner on the South Section Line Section 12, T.32N.-R.10E.
have been re-established by prorating the distance be-
tween Section $\frac{11\frac{1}{2}}{15}$ and $\frac{12\frac{1}{2}}{15}$ T.32N.-R.10E. into four (4)
equal parts. All of the $\frac{1}{16}$ established corners checked
with photographs showing physical features of the Land
in relation to their location on the ground. All of
the corners re-established and the original Section
Corners have been identified with MASS CAPS and records
or location filed with County Surveyors Office.



William F. Kelly 21 May 1974