STUART L.

**FOLTZ** 

S-1170

**WOODRUFF** 

O = Corner	monument	restored.
------------	----------	-----------

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Not set during the original survey in 1865.

Description of corner evidence found:

Correct location for this corner was determined by a closed traverse of Section 32, positioning this corner midway between the North one-quarter corner and the Northeast section corner.

\* A Forest County aluminum monument and an old wood post were found bearing N80°E, 17.4 feet from the correct corner location.

Description of monument and accessories I established to perpetuate the original location of this corner.

Iron Rod set, 1-1/4" Diameter and 30" long.

6" Maple N88°E, 9.8 feet 8" Maple N06°W, 27.7 feet

