FBILLIFID	IANID	CUBNED	RESTORATION
	LAND	COMILIA	NESIONATION

Index No. R23

History of original corner establishment:

Original subdivision by William Daugherty 4 Aug. - 9 Aug. 1859

Tamarac 10 N49W 5 Lks. Tamarac 10 S30W 20 Lks.

Description of corner evidence found:

Found old broken off post and two post points

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 14" iron pipe with steel cap at location of post points.

Ties:

Cedar	8	N57E	14.42 feet
Cedar	10	N13W	14.42 feet 12.89 feet

Dated at Crandon , Wis., this 29th day of January Registration Nos-887.

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 29th day of January , 19.80.

(Register of Dodds)

Document Number

117461

THOMAS R

ARNOTT

S-887

CRANDON

By......Deputy