43713162000

HC Miller Company ()

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

| Index | No | L-13 | |
|--------|---|------|--|
| IIIUCA | • | | |

| County of | | | onsi | | } s | c |
|---|-----------------|--|--|---------------------|--------------------------------------|---|
| County of | Fc | rest | | ••••••• | } . | J. |
| certify that of Mar evidence of corner of 13 East as described I established as described | on the the days | he | ast ecti urth d that | on 16 Princip from | 93 er Sorth bal M this e | I found Range eridian, vidence essories |
| as described location of t | l her | eon to orner. | | | | |
| Resident wi | tness | es: | | | | |
| | | | | | | |
| | . | •••••••••••••••••••••••••••••••••••••• | •••••••••••••••••••••••••••••••••••••• | | | . |
| | | | | | | |
| | | | | | | |
| |] | | <u> </u> | | | |
| | i | | | | | |
| | | | | | | |
| | | | | | | |
| | | SECT | | <u>16</u> _ | | |
| | | | | <u>16</u> _ | | |
| | | | | | | |
| | | <u>SECT</u> | | | | |

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by J.L. Nowlin. North between Sections 15 and 16, at 40.00 chains, set Quarter Section Post, from which the following bear;

 Tamarack
 8"
 N08 E
 20 lks.

 Tamarack
 6"
 S07 W
 5 lks.

Description of corner evidence found:

No corner evidence was recovered.

I re-established the corner position at proportionate distance and on line between the Northeast and Southeast Section Corners of Section 16.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position, set a 2½ inch diameter aluminum pipe monument, 5 feet long, 3 inches above the ground surface, with an aluminum cap stamped; T37N R13E, 1/4, S16, S15, 1993, S-1634. From which the following new blazed and scribed bearing trees bear; (Measurements taken to a nail in side of tree)

NO BEARING TREES AVAILABLE:

Steel Sign Post, 6 ft. long, North, 1.05 feet
" " East, 1.00 feet

| Dated at | Iron River, MI | ,XXXX, this | 22nd | dav of | April | |
|---------------|---|-----------------|--------------|-------------------|------------|-------------------------|
| Signature | Hary L. Lison | Title | Land S | urveyor | Regi | istration No.S-1634 |
| _ | (County Surveyor, Register | ed Land Surveyo | or, or other | duly authorized o | official) | |
| Office of Reg | ister of Deeds, County of | HOL | est | | , L hereby | certify that the within |
| instrument w | vas filed in this office for rec | ord on the | | day | of CLUBIL | 1993 |
| at/.25= 0 | (County Surveyor, Register ister of Deeds, County of vas filed in this office for recollect | · • | | | | |
| - | | | | | | |
| | (Register of Deed | | | | | |


(Register of Deeds)


Deputy

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?





PISONI

S-1634

IRON RIVER.

MI

Gary L. Pisoni

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and

on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Hay L. Feson. June 25, 1993

Survey requested by: District Ranger Date