H. C. MILLER CO., MILWAUKER 448643

R9-5680-5 (7/15/64)

CERTIFIED LAND CORNER RESTORATION		
State of Wisconsin County of Forest	S.	•
I found evidence of the <u>North</u> Township 37 North	, do hereby certify that on the 7th on Ouarter corner of Sourth, Range 15 East Fourth nce I established a new monument and accesses corner:	ection 9 Principal Meridian, as described
Description of original monument	and accessories and subsequent restorations:	
Surveyed in 1865 by 39.55 chains west con Set post Fir 7", bears N33E, Ironwood 6", bears Se	rrected 12 lks.	
Description of corner evidence for	und:	
Chained 39.5 chains of the second 10 found iron in post hole. No evaluation being in agreement with the second second in agreement with the second se	West from Section Corner between pipe and remains of old post. idence of original B.T.'s found ith corners in area and other favailable evidence of corner loss.	Pipe had been set . This iron pipe eatures I accept
Replaced iron pipe w	essories I established to perpetuate the original ith a 2 inch inside diameter, gong, filled with concrete, with	alvanized wrought
T37N R15E 1 S4 4 S9 1970	From which the following New bearing trees bear: Sugar 18", bears N44E, Hemlock14", bears N63W, Iron fence post 1 foot North	66.09 feet 53.31 feet
S-802	Danidont mituana	JEAN F. RESVICK RHINELANDER,
	1970	in, this 1/2 day of SUR
Sec. 9	(County Surveyor, Registered Land Surveyor,	Title Cadastral Surveyor or other duly authorized official) DOCUMENT NUMBER 98914
		inty of Forest
Corner monument restored	I hereby certify that the within instrument woon the 23rd day of October No.COEN FR Page No E-11 of RESTORATIONS	1970, and was filed in Book County Records.
Township 37 North, Rang	RESTORATIONS Signature Signature 15 East Section 9 Index N	Title Register of Deeds o. E-11, Page No.