State	of Wisc	onsin	} ss.
County of	Forest		5 33.
certify that ofFebru evidence of corner of Township 12 East as described I established	on the ary the South Section A new modern to	sth 5th 19.9 west Sect on 31 ourth Princip d that from to	on lound lon lond lond lond lond lond lond lon
Resident wi	tnesses:		
****		<i>3</i> 7	******
******	*******	;	***************************************
	l	1	
	l 	1	1
	!	<u>-</u>	
	l	i I	t
	SECT I	<u> </u>	! !
	 	1	' !
	l ₁ .	1	
	-	' i	<u>-</u>
	' !	1	
		<u> </u>	
= Corner	monument	trestored	

History of original corner establishment Original Government Survey in Dependent Resurvey in 1937 by T38N R12E, at 78.77 chains, to North, Ranges 11 and 12 East, Set a concrete monument, 2 fee T38N, R11E, R12E, S36, S31, St Cedar 5" N68°45'E	1858 by Alfred Wesson Cook. Whe point for the is determined et long, 6 inch	est on the Some original configuration from remains of the second state of the second	rner of Town of original r, with a br	ships 37 and 38 bearing trees. ass cap marked; ing bear;
	23.10 feet			0'W 25.08 feet
Description of corner evidence found: Found monument as described as 2 inch diameter iron pipe with	nd in place. No	rtheast and a	longside mon	ument, found a
Found the following bearing to	rees.;			
Cedar 11"	n68°45 ' Е	49.28	feet	
Cedar 11"	S25°45 ' E	23.55	feet	
Cedar(Stump)	S42°00'W	36.96	feet	
Cedar (Stump)	N75°30'W	25.08	feet	
Description of monument and accessoring Blazed and scribed the follows Cedar 11" Spruce 9"	-	-	feet	this corner.
Set;				-{ 1
Steel Sign Post	South	1.00	feet	\
Painted and attached bearing	tree signs to a	11 bearing tre	ees.	
Dated at Hiles	•	•		•
Signature William B. Coch (County Surveyor, Register	Land Surveyor, or o	d Surveyor	official)	egistration No. S-1107
Office of Register of Deeds, County of	Forest	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	I herel	y certify that the within
instrument was filed in this office for reat 1:00 o'clock. P. M.	cord on the 8th	day	of March	19.90

Taul Achentrenner (Register of Deeds)

(a) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or recetablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(gkh) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as

evidence or used for proportioning in determining the corner location? 9" Spruce (New Bearing Tree) N16°W, 14.80 feet 2" Iron Pipe Northeast, Alongside Monument 11" Cedar (GLO Bearing Tree) N68°45'E, 49.28 feet S36 S31 T38N Township Corner .S6 T37N R11E | R12E Steel Sign Post South, 1.00 feet Affix WISCONS. 11" Cedar (New Bearing Tree)

William B. Cochrane (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

S35°W, 38.70 feet

Signature

Survey requested by; District Ranger Date

11" Cedar (GLO Bearing Tree)

S25°45'E, 23.55 feet

WILLIAM B.

COCHRANE

HILES,

WISCONSIN

· S-1107

85-A	ĮΣ	26273
FUKM NO. 985-A	H.C.Miller Company	Š
ž	31	Stock

NUMBER	
Z	-
IN:	
55	

U.S. F	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
--------	--------	------	--------	----------	--------

Index	No	A-1
IIIGEX	140	

State of Wisconsin } ss.
County of Forest
I William B. Cochrane , do hereby certify that on the 5th day of February , 19 90 , I found evidence of the Northwest Section corner of Section 6 Township 37 , North, Range 12 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.
Resident witnesses:
SECTION 6
1 1 1

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1858 by Alfred Millard.

Dependent Resurvey in 1937 by Wesson Cook. West on the South boundary of Section 31 T38N R12E, at 78.77 chains, the point for the original corner of Townships 37 and 38 North, and Ranges 11 and 12 East, is determined from remains of original bearing trees. Set a concrete monument, 2 feet long, 6 inches in diameter, with a brass tablet marked; T38N, R11E, R12E, S36, S31, S1, S6, T37N, 1937. From which the following bear;

 Cedar
 5"
 N68°45'E
 48.84 feet
 Cedar
 5"
 S42°00'W
 36.96 feet

 Cedar
 5"
 S25°45'E
 23.10 feet
 Cedar
 6"
 N75°30'W
 25.08 feet

Description of corner evidence found:

Found monument as described and in place. Northeast and alongside monument, found a 2 inch diameter iron pipe with a threaded cap stamped to identify the corner.

Found the following bearing trees;

Cedar	11"	N68°45'E	49.28	feet
Cedar	11"	S25°45'E	23.55	feet
Cedar(Stump)		S42°00'W	36.96	feet
Cedar(Stump)		N75°30'W	25.08	feet

Description of monument and accessories I established to perpetuate the original location of this corner. Blazed and scribed the following new bearing trees;

	Cedar Spruce		L'' 9''	S35°W N16°W	38.70 14.80	
Set;	Steel Sign	Post		South	1.00	feet

Painted and attached bearing tree signs to all bearing trees.

Dated at Hiles					
Signature William B. Co (County Surveyor,	Registered Land Surve	Land Surv	eyor	Registra	ation No.S-1107
Office of Register of Deeds, Coun instrument was filed in this office at 1:00 o'clock P. M. (Register	ty of Fore for record on the	st 8th	day o	, I hereby cer March	tify that the within 19 90

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

9" Spruce(New bearing tree) N16°W, 14.80 feet 2" Iron Pipe NE, Alongside Monument 11" Cedar(GLO Bearing Tree) N68°45'E, 49.28 feet Township Corner S36 S31 R11E R12E Steel Sign Post South, 1.00 feet 11" Cedar(New Bearing Tree) S35°W, 38.70 feet Land Surveyor Scal NSCOMS WILLIAM B. 11" Cedar(GLO Bearing Tree) COCHRANE S25°45'E, 23.55 feet

(i) William B. Cochrane
(type or print name) certify that the corner location shown
on this record was determined by me or under my direction and
control and that this U.S. Public Land Survey Monument Record is
correct and complete to the best of my knowledge and belief.

William B. Cochrane 2/6/90

Survey requested by;

Jam Dordin

3/1/90

S-1107 HILES, WISCONSIN

SURY

District Ranger

Date