I William B. C	ochrane	., do hereby
certify that on theof July	28 th	day
of July	19. <sup>9</sup>	1 found
evidence of the Nor	th Quarter	
corner of Secti	on 35	
Township 39		orth. Range
13 East	Fourth Principa	il Meridian,
as described hereon;	<del>-</del>	
I established a new	monument and	accessories
as described hereon	to perpetuate	the original
location of this corne	• •	_

Resident witnesses:		
	· · · · · · · · · · · · · · · · · · ·	

			<del>, -</del>
1			1
ļ .		]	1
ì	l	l	I .
	l :	1	1
	<u> </u>	!	<u> </u>
-	<u> </u>		1 · · · · · · · · · · · · · · · · · · ·
	1	I	I
f	1	! .	ı
	l	أسرح والم	[
<u> </u>	· _SECTI	! <u>0</u> N_3 <u>5</u>	<u> </u>
	!		
	l .		1
}	1		l
· ·			Į.
<b> </b>	<u> </u>	' <b>_</b>	<u> </u>
	1		!
1	l	,	l
	1	<b>,</b>	l
ļ I	1		ļ.
	1		t

= Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Original Government Survey by William E. Daugherty in 1865.

West corrected between sections 26 and 35, at 40.31 chains set post form which:

N13°E 17 1ks Hemlock S17°W 26 1ks Tamarack

Description of corner evidence found:

7/18/73 Jean Resvick searched for corner. At alpoint N17°E 17.16' from a Tamarack stump, found noevidence of the original post. Local bearing trees bear:

S37°E 19.23 feet Spruce S82°W 12.80 feet Spruce

Description of monument and accessories I established to perpetuate the original location of this corner.

From ties to local bearing trees as found by Jean Resvick in 1973. I accept this position as the only remaining evidence of the corner position which has long been accepted as such. Set a 2½X60" aluminum pipe monument 4 feet in the ground with an aluminum cap stamped: T39N R13E, 1/4, S26, S35, 1994, S-1107. From which:

N15°E 24.16 feet B. Spruce N73°W 17,79 feet B. Spruce 1.00 feet South Steel sign post

Dated at	Hi <b>l</b> es	, Wis., this	21 st	day of	December	. 19. <sup>94</sup>
	Tilliam B. C.	ochrane Title	Land Sur	veyor	Registration No	
_	(County Surveyor	Registered Land Surveyo	r, or other dul	y authorized official)		
Office of Re	gister of Deeds, Cou	nty of	21 m	<i>,</i>	I hereby certify that t	he within
instrument at 2:30	was filed in this office o'clock	e for record on the	254	day of	I hereby certify that t	<b>مگر</b> 19.

(Register of Deeds)

u )	Describe any material discrepancy between the location of the corner as restored or
	reestablished and the location of that corner as proviously restored or reestablished
•	by distance and direction. Show the discrepancy on the plan view drawing under (d),
	above. Show the distances between the corner as previously restored or reestablished
	and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness.
	monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an oblicerated evidence location, or, (2) a found perpetuated location?

Restored through accepted local bearing trees and ties to possiable original bearing tree remains.

(gkh) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Spruce 8"
N15°E 24.16'

Steel sign post
South 1.00'

WILLIAM B.
COCHRANE
S-1107
HILES,
WISCONSIN

SURVEY

S

(i) I.

(type or print name) certify that the corner location shown un this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

\*\*\*

William B. Cochrane 12/21/94