


SURVEY MAP
of the Northeast quarter of the Northeast quarter, and of the Southeast quarter of the Northeast quarter of Section 3 and of the Northwest quarter of the Northwest of Section 2, all in Township 36 North, Range 12 East, Town of Crandon, Forest County, Wisconsin

- Federal Forest Service Monument visited
 - Federal Forest Service Monument location computed from survey data received from the Federal Forest Service
 - iron pipe found
 - 1" x 24" iron pipe set
 - rail road spike set
- existing fence lines - the fence lines shown hereon are very old and down on the ground with very few post standing, hard to recover under snow cover.
- bearings referenced to bearing on the east half of the north line of Section 2, furnished by the U.S. Forest Service from their survey of the east-west Township line.
- no hard evidence of original Gov't Corners found

I, Norman A. Harrison, hereby certify that under the direction of Chicago Title Insurance Company/J. bushnell Nielsen/ Ms. Donna Christensen, I have surveyed the Northeast quarter of the Northeast quarter and the Southeast quarter of the Northeast quarter of Section 3, Township 36 North, Range 12 East according to description furnished; that under the direction of Condon Oil Company/ Tom Pearson, I have surveyed the Northwest quarter of the Northwest of Section 2, Township 36 North, Range 12 East according to description furnished, all in the Town of Crandon, Forest County, Wisconsin and that to the best of my knowledge and belief the maps on Sheet 1 and on Sheet 2 are a correct representation of that survey.

date: April 17, 1995 *Norman A. Harrison*
Norman A. Harrison



SCALE: 1 in. = 400 ft.



prepared by: N.A.H.
order no. 339
sheet 1 of 2

FOREST CO SURVEYOR
FILE # 361203-19950417
DATE _____ BY _____

found 3/4" diameter hole in wood post lying on rocks