

CERTIFIED LAND CORNER RESTORATION

Index No. G-9

State of Wisconsin }
County of Lanlade } ss.


History of original corner establishment:

Corner Established in 1939 Resurvey

I Raymond J. Hallisy, do hereby certify that on the 29th day of April, 1978, I found evidence of the EAST 1/4 W.C. corner of Section 8 Township 32, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4 inch IRON PIPE WITH BRASS CAP
1/4 inch IRON PIPE 9 inches EAST




Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW B.T.S
ASPEN 8 inch S 58° W 14 FT 10 inches
ASPEN 5 inch N 48° W 17 FT 2 inches
ASPEN 6 inch N 21° E 14 FT 7 inches

FORM 985 H. C. MILLER CO., MILWAUKEE

T32N R12E



○ = Corner monument restored.

Dated at Antigo, Wis., this 29th day of April, 1978.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy