

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(Prepared and as required by S. A-E 7.08 WI Administrative Code)	•
The South 1/4 corner of Section 14, T. 33 N., R. 10 E., Langla Corner was (check all that apply)	de County, Wi
Restored through acceptance of an obliterated evidence location.	
Restored through acceptance of a found perpetuated location.  Determined to be lost and re-established through proportionate methods.	
(show bearings and distances to PLSS corners used for proportioning.)	
Restored/recovered/re-established in a location that differs from a previously	
established position. (Show difference in plan view below.)  Check here if additional information is shown on the reverse side of this form.	
Describe record evidence, recovered physical evidence, occupational evidence, testimor and all other evidence considered in the recovery/restoration of the corner.	nial evidence,
Oct. 1860 - Corner was not set in original survey of Township. Original surveyor called the area a posts on each side.	
1939 - GLO Resurvey - Corner set at midpoint between adjacent section corners set 4" bras concrete, with N45°E, 6.60' tamarack post, and S45°W, 6.60' tamarack post for ties.	•
2007 - I retraced GLO Resurvey and found the 4" Brass Cap monument in concrete in place gone. Corner is approximately flush with the vegetative/ice surface of the marsh.	e. 1939 bearing objects were
Physical description of the monument set:	
I left the monument in place and tied out as follows -	
Describe the accessories used to perpetuate the location of the corner. Include a plan view drawing found/set. Describe measuring point on bearing trees. Show any topographic features that would	ng and indicate accessories I aid in future recovery of the comer.
* All Bearing Trees with aluminum	, BE
signs, no blazes.	GOUNTY
<b>u</b>	GS F
్ర్మ్ ∳ 3" Tamarack	Y COORDINA
17°03 15.04'	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
<b>≥</b> ∫ ·	DED:
S 78°53'16" W  S 78°53'16" W  33.76.37.6	TO TO TO
S 78°53'16" W 33, 70'3>	HE L
2/0.16. 1	ANGI A GRI
SW CORNER BRASS CAPPED IRON PIPE FOUND White Vinyl post	THE LANGLADE (STEM GRID.
IRON PIPE FOUND White Vinyl post	
\$\tag{\sigma}	
lacksquare	001711444
5" Tamarack	The SOUTH 1/4
	Corner of Section 14
	T. 33 N , R 10 E. Langlade County, Wi
	zangiado ovaniy, m
SURVEYORS SEAL	
	<b>1</b> 4
	NDEX No.
Timothy J. Rusch	Z o
I,	
Timothy J. Rusch  I	○ = Location of corner