

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(Prepared and as required by S. A-E 7.08 Wisconsin Administrative Code)

The center 1/4 corner of Section 7, T. 33 N., R 11 E., Langlade County, WI

43311072020

Corner was: (check all that apply)

- Restored through acceptance of an obliterated evidence location.
- Restored through acceptance of a found perpetuated location.
- Determined to be lost and reestablished through proportionate methods.
(Show bearings and distances to PLSS corners used for proportioning)
- Restored/recovered/reestablished in a location that differs from a previously established position. (Show difference in plan view below.)
- Check here if additional information is shown on the reverse side of this form.

Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of corner.

In 1983, William F. Kelly subdivided said section and set a 2.5" iron pipe at his location of intersection of the 1/4 lines.

In 2004, Dean A. Williams reestablished the said corner at the intersection of 1/4 lines.

Physical description of the monument set:

3.5" brass cap on a 2.5" x 30" iron pipe. Standard county monument.

Describe the accessories used to perpetuate the location of the corner. Include a plan view drawing and indicate accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would aid in future recovery of the corner.

