## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin  County of Forest ss.
I Milo E. Stefan , do hereby certify that on the 9th day of September , 19.81.  I found evidence of the South Quarter corner of Section 1  Township 37 North , Range 15 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to per petuate the original location of this corner:
Description of original monument and accessories and subsequent restorations:
True line West corrected between Sections 1 - 12 40.45 set ½ post 6" Fir, S67E, 10 links 6" Fir, N29W, 4 links

## Description of corner evidence found:

- 1) Post hole with newly made references (record lost)
  14" Hemlock, scribed "45", "BT", S5E, 11.48 feet
  - 12" Hemlock stump, reversed impression of "BT", N33E, 17.0 feet
- 2) 1934 truck trail survey calls wood post 241 feet East of Forest Road 2159 center line distance is 241.8 feet to post hole from approximate road center line.

Description of monument and accessories I established to perpetuate the location of this corner:

Placed a 2" x 30" aluminum monument in post hole 24" in the ground with mound of stone.


## References:

Red Maple 12", N83E, 55.87 feet
Hemlock 14", S5E, 11.48 feet (old BT, record lost)
Hemlock 12", N11W, 24.10 feet
Steel Sign Post, Northeast, 1.0 feet

DOCUMENT NO.

124205





37 North Range 15 East Section