CEI	RTIFIED LAND CORNER RESTORATION
State of Wisconsin State	
I found evidence of the Sout Township 34 North	day of October, 19 80, heast corner of Section 14. Range 16 East Fourth Principal Meridian, as described ce I established a new monument and accessories as described hereon to personner:
Description of original monument	and accessories and subsequent restorations:
Surveyed by James McBride in Set a wood post. Spruce, 6", N23°E, 24 links Spruce, 6", S43°E, 10 links Cedar, 10", S43°W, 21 links Cedar, 12", N32°W, 20 links	
Description of corner evidence fou	nd:
Posts points and 14" iron posts No BT'S recovered Swamp calls north and west	
At corner position set a 2	essories I established to perpetuate the location of this corner: inch by 5 foot aluminum pipe with cap stamped:
T34N, R16E, S13, S14, S23, S From which the following bear Tamarack, 10", N73°E, 42.84 Cedar, 6", S55°E, 14.78 feet Tamarack, 8", S25°W, 17.39 S Cedar, 10", N62°W, 29.77 feet	feet feet MILO E-
	Resident witnesses Dated at Laona Wisconsin, this 4 day of November 19.80 Signature Milo E. Stefan Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official) Surveyors Registration No Office of Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record
- Corner monument restored	on the 2nd day of June 1981, and was filed in Book