## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	•		
County of Forest	<b>}.</b>		
I Milo E. Stefan I found evidence of the East Township 35 North hereon; and that from this evidence petuate the original location of the	Quarter Range 16 East ice I established a new n	corner of <u>Section</u> , Fourth Princip	n 20 pal Meridian, as described
Description of original monument		equent restorations:	
Surveyed in 1858 by James North between sections 20 at 40.00 set $\frac{1}{4}$ section post Tamarack 10", S2°E, 226 Tamarack 10", S7°W, 271	nd 21. links		***
Description of corner evidence for	ınd:		
Description of monument and acc	essories I established to	perpetuate the location of the	his corner:
Replace post and post point 5' long capped with an alum T35N, R16E, \(\frac{1}{4}\), S2O, S21, 19  Blazed and scribed new bear Black Spruce, 6", S59°E, 45  Tamarack, 2", S10°W, 37.28  Black Spruce, 3", N79°W, 20  Steel sign post, N45°E, 1.0	inum tablet stamped: 79, S-1558. ing trees: 6.36 feet feet 0.46 feet	<b>-</b>	MILO E- STEFAN S-1558 RHINELANDER, WIS.
Sec. 20	(County Surveyor, Reg Surveyors Registration ) Office of Register	Stefan Title gistered Land Surveyor, or other	f Forest
Corner monument restored  ———————————————————————————————————	on the 2nd day on No. Page	Noof Count	81, and was filed in Book ty Records.
	e <u>16E</u> J., Section 3516202000		-9, Page No
ι .	~~ / / <b>/</b>		