Document Number 19359

REGISTER'S OFFICE
Forest County, Wi

Received for record this 3/5T day

of December AD -2008

at 10:10 o'clock A M and
recorded in Vol Corner Restoration
on page L-21

Kay Sevanson

Deputy REGISTER

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(As Required by WI Adm. Code)

History of original corner establishment and subsequent restorations and descriptions of any record, monument, occupational, testimonial or other evidence considered:

- 1859 William E. Daugherty, set quarter corner section post and made the following B.T.'s:

 Hemlock, 8", N 81° W, 10 lks., 6.60 feet.

 Hemlock, 10", S 71° E, 14 lks., 9.24 feet.
- 1919 I.R. Ritter set an iron pipe at quarter corner position and made the following B.T.'s:

 Tamarack, 10", S 44° W, 4.5 lks., 2.97 feet.

 Cedar, 8", S 04° W, 17.5 lks., 11.55 feet.
- I set corner at proportionate distance and on line between the Northwest Corner and the Southwest corner of Section 13. Corner falls 12 feet North of Centerline of Town road.
 I set a 2" X 30" Forest County Aluminum Pipe Monument from which the following bear:
 1" X 32" Iron Pipe, N 04° E, 21.35 feet.

1" X 32" Iron Pipe, N 04" E, 21.35 feet. Black Spruce, 14", N 40" E, 23.49 feet. Cedar, 9", S 29" E, 61.05 feet. Hemlock, 12", S 40" W, 66.89 feet.

Corner was: (Check All That Apply)

Restored through acceptance of an obliterated evidence location.
Restored through acceptance of a found perpetuated location.

Considered a lost corner and reestablished through lost corner proportionate methods (include a plan view drawing showing distances and directions to other Public Land Survey Corners used for proportioning and determining the corner location).

Restored or reestablished in a location that differs from a previous restoration or reestablishment (include a plan view drawing and indicate what was set and/or found).

Describe the monument and accessories used to perpetuate the location of this corner (include a plan view drawing and indicate what was set and/or found).

