rebrielen	IAND	CUDNED	DECTABATION	. [
ントハールート	LAND	CORNER	RESTORATION	¥

		7	1 1
Index	No.	Ĺ,	<u> </u>

History of original corner establishment:

Origin of this C 1/4 corner is unknown. Corner has been in existence for many years and recognized by adjacent land owners as the corner.

Description of corner evidence found:

Recovered a 3" iron pipe with concrete in the upper half, projecting 18" above ground. Corner sets in a wet alder swamp. This area had once been flooded from a beaver dam. No BT's were in evidence.


Corner sets 2 chains north of Highway U.S. 8.


Description of monument and accessories I established to perpetuate the original location of this corner. Replaced 3" iron pipe with 22" Berntsen A-1 Federal Monument, stamped. No trees available for BT's. Set two 12" iron pipes for reference marks. T37N R15E #1 - North 25 links, projects $2\frac{1}{2}$ above ground. #2 - East 20 links, projects $2\frac{1}{2}$! above ground. 5498 - 1976Monument and reference marks painted blue.

Dated at Rhinela	ander , v	Vis., this	6th	.day of	Septemb	er	, 1976
Signature Lieb Count	ty Surveyor, Régistered I	Title Regi Land Surveyor,	stered Lar or other duly a	nd Surveyo: uthorized officia	rR	egistration	ı NoŞ <u>-</u> 498
Office of Register of Dinstrument was filed in	eeds, County ofthis office for record	on the	t 9th	day of	, I herel	oy certify ember	that the with 76
at 3:45 o'clock	P. M. Statisms			DOCUMENT			
By.	(Register of Doeds)		Deputy				

State of Wisconsin County of Forest

Philip T. Hansen, do hereby certify that on the 13th day of September , 19.76, I found evidence of the C1/4 corner of Section 28 15 East, Fourth Principal Meridian, as described hereon; and that from this evidence established a new monument and accessories as described hereon to perpetuate the original





O = Corner monument restored.