

OCCUPIED N. LINE GOV'T LOT 2  
 OCCUPIED SE CORNER GOV'T LOT 1  
 COMPUTED SE CORNER GOV'T LOT 1  
 BEARING & DISTANCE FROM OCCUPIED CORNER TO COMPUTED CORNER IS S14° 46'15"E - 78.53'  
 VOL 157 DEEDS PG 16  
 VOL 188 DEEDS PG 370  
 ALL OF THESE LOTS START AT THE NW CORNER OF GOV'T LOT 2 AT A GALVANIZED IRON PIPE. THEN SOUTH TO THE LAKE EAST 100 NORTH TO THE 40 LINE THE WEST 100 TO POB. WE USED THE BEARING OF THE FOUND GALVANIZED PIPE TO WHAT WE BELIEVE IS THE MC OF THE NORTH-SOUTH 1/4 LINE. THEN WE CAME ACROSS START AT THE GALVANIZED PIPE EAST ALONG THE OCCUPIED 40 LINE.  
 FD 1" I. PIPE ASSUMED TO BE THE MEANDER CORNER OF THE NORTH-SOUTH 1/4 LINE, PIPE WAS ALSO FOUND BY BILL KELLY IN VOL 3 CSM PG 116  
 ICKEREL LAKE  
 NORTH  
 FOREST CO SURVEYOR  
 FILE # 341329-  
 DATE \_\_\_\_\_ BY \_\_\_\_\_  
 VOL 120 DEEDS PG 797  
 VOL 199 DEEDS PG 243  
 VOL 199 DEEDS PG 245-247  
 VOL 120 DEEDS PG 779  
 VOL 120 DEEDS PG 796  
 VOL 199 DEEDS PG 248  
 VOL 162 DEEDS PG 729  
 S 100' W. OF RD  
 N E-W 1/4 LINE  
 RECORDED AS NE COR GOV'T LOT 2  
 PRIVATE ROAD DRIVE  
 CABIN  
 SHED  
 HOUSE  
 VENT  
 GARAGE  
 HOUSE  
 HOUSE  
 GARAGE  
 60.5'  
 100'  
 150.90'  
 50.21'  
 12.21'  
 529.89'  
 280.76'  
 146.37'  
 504.32.38"E  
 N85°50'53"E  
 S85°50'13"W 563'±  
 N05°06'49"W 214.15'  
 45'±  
 33'±  
 43'±  
 21'±  
 32'±  
 506.00'  
 538'±  
 482'±  
 460.58'  
 N89°48'39"E  
 N89°48'39"E  
 N15°25'23"E 181.70'  
 N00°18'16"E  
 S89°58'11"W 194.59'  
 570.50' VOL 199  
 614'±  
 60.5'

THESE DEEDS COME FROM THE NE COR GOV'T LOT 2  
 WE USED THE FOUND PIPE TO DETERMINE THE POSITION OF THE NORTH AND SOUTH LINES OF THE DEEDS. IF YOU USE AN INTERSECTION OF THE E. LINE OF GOV'T LOT 2 AND THE OCCUPIED E-W 40 LINE YOU START TO HAVE ENCROACHMENT PROBLEMS. THE SEPTIC VENT IS OVER THE LINE AND ONE LINE GOES THROUGH THE A HOUSE.

THESE DEEDS COME FROM THE NE COR GOV'T LOT 2  
WE USED THE FOUND PIPE TO DETERMINE THE POSITION OF  
THE NORTH AND SOUTH LINES OF THE DEEDS. IF YOU USE AN  
INTERSECTION OF THE E. LINE OF GOV'T LOT 2 AND THE OCCUPIED  
E-W 40 LINE YOU START TO HAVE ENCROACHMENT PROBLEMS. THE  
SEPTIC VENT IS OVER THE LINE AND ONE LINE GOES THROUGH THE  
A HOUSE.