

Stock No. 26273

Sheet 2 of 3

SURVEY NOTES

This survey was made by the U. S. Department of Agriculture, Forest Service, for the purpose of restoring and establishing corners on the perimeter of Section 2 for establishing subdivisional corners within Section 2 and for locating and marking the boundaries of U. S. Government land on the perimeter and within Section 2, Township 35 North, Range 16 East, Fourth Principal Meridian, Forest County, Wisconsin.

The U. S. Government lands in this section were acquired in 1936.

The original government subdivision survey of this township was made in 1858. A subsequent survey was made in 1928 by Goodman Lumber Company.

The corner positions recovered, restored and established by this survey are marked by the monument described in the map legend.

The corner positions established were located to an accuracy of one part in 3000.

The bearings between corner positions are true bearings as determined by solar observations.

The field notes of this survey and a copy of this plat are on file in the Forest Supervisor's Office at Rhinelander, Wisconsin.

CORNERS RECOVERED AND RESTORED

1. Corner Common to Sections 2, 3, 34 and 35.
Corner recovered as set by Milo Stefan (RLS), certificate on file in Forest County.
2. Corner Common to Sections 1, 2, 35 and 36.
Corner recovered as set by Jean Resvick (RLS), certificate on file in Forest County.
3. Corner Common to Sections 1, 2, 11 and 12.
Corner recovered as set by Jean Resvick (RLS), certificate on file in Forest County.
4. Corner Common to Sections 2, 3, 10 and 11.
Corner recovered as set by Jean Resvick (RLS), certificate on file in Forest County.
5. Quarter Corner Common to Sections 3 and 34.
Corner recovered as set by Milo Stefan (RLS), certificate on file in Forest County.
6. Quarter Corner Common to Sections 1 and 2.
Corner recovered as set by Jean Resvick (RLS), certificate on file in Forest County.
7. Quarter Corner Common to Sections 2 and 11.
Corner recovered as set by Alan Harrison (RLS), certificate on file in Forest County.
8. Quarter Corner Common to Sections 2 and 3.
Corner recovered as set by Jean Resvick (RLS), certificate on file in Forest County.

Stock No. 26273

Sheet 3 of 3

CORNERS ESTABLISHED1. South Sixteenth Corner to Sections 2 and 3.

Corner position established midpoint and on line between quarter corner north and section corner south.

Corner References:

Sugar	11"	S.73°E.	36.80 feet
Sugar	10"	S.14°W.	10.52 feet
Steel Sign Post		Southwest	0.75 feet
Iron Pipe	1½"	S.23°W.	2.16 feet

2. West Sixteenth Corner to Sections 2 and 11.

Corner position established midpoint and on line between section corner west and quarter corner east.

Corner References:

Sugar	6"	N.34°E.	71.51 feet
Sugar	6"	N.20°W.	80.56 feet
Steel Sign Post		Southwest	0.75 feet

3. Southwest Sixteenth Corner to Section 2.

Corner position established at the intersection of the south and west sixteenth lines of Section 2.

Corner References:


Sugar	8"	N.39°E.	23.57 feet
Sugar	6"	S.04°W.	15.10 feet
Steel Sign Post		Southwest	0.80 feet

SURVEYOR'S AFFIDAVIT


State of Wisconsin] SS
County of Forest]

I, Alan D. Harrison, Land Surveyor, U.S.D.A. Forest Service and a Registered Land Surveyor in the State of Wisconsin, do hereby certify that I have surveyed and subdivided Section 2, Township 35 North, Range 16 East, Fourth Principal Meridian, State of Wisconsin.

The plat map and the notes herewith are a correct representation of the land surveyed and divided. I have surveyed and subdivided said section in accordance with the rules for survey of the public lands and with the statutes of the State of Wisconsin.



Alan D. Harrison
LAND SURVEYOR, U.S.D.A. Forest Service
R.L.S. Number S-1651
State of Wisconsin



Plat ready for filing:

Date of Survey: 1989

Dale Staege