

**LEGEND**

- Section Corner
  - 1/16 Corner
  - ▲ 10" Steel pipe 4'-5' high
  - 3/4" x 24" iron rod and cap set
- 1" = 150'

West 1/4 Corner  
1-37-16  
Found 1-1/4" iron pipe

NW 1/4 SW 1/4

NE 1/4 SW 1/4

SW 1/4 SW 1/4

SE 1/4 SW 1/4

S00°51'06"W 1319.48'

S00°49'31"W  
West line SE 1/4 SW 1/4

**SURVEYOR'S NOTE**  
Survey by Norman Harrison dated 6-26-2009 state that this corner was a 1" iron pipe. No iron pipe found. I doubled distance between West 1/4 Corner Section 1 and South 1/16 Corner on West Section line and extended line through it to set Corner.

Southwest Corner  
1-37-16  
Set P/K nail

Bearings referenced to the East line of Southeast 1/4 of Section 1 (N00°32'56"E)




**CERTIFICATE**

I, Hugh W. Guy Jr, surveyor, hereby certify that I have under the direction of Stanley Frydrych, that I have surveyed the lands hereon described.

*[Signature]*  
Hugh W. Guy Jr. RLS #1301

DATED this 4th day of September, 2010.



**DESCRIPTION**

Retracement survey of large field encroachment as shown on survey by Norman Harrison dated 6-26-2009 located in part of the Southwest 1/4 of the Southwest 1/4 and in part of the Southeast 1/4 of the Southwest 1/4 ALL in Section 1, Town 37 North, Range 16 East, Forest County Wisconsin. I did not do a Section Split of Section 1 to verify Mr. Harrison's location of the East-West 1/8 line in the Southwest 1/4 of Section 1.