

Stock No. 26273

T39N R14E - SECTION 9

page 2 of 5

SURVEY NOTES

This plat of survey for Section 9, Township 39 North, Range 14 East is the product of a Photogrammetric Project linked with Global Satellite Positioning procedures to establish the co-ordinate values used as control to recover and restore lost Section and Quarter Section Corners and to establish positions for Sixteenth and Property Corners within the Sections in this project area.

The 10 G.P.S. Stations were assigned State Plane Co-ordinate Values. The values were then transferred to the target locations for ground control through photogrammetric bridging.

All bearings are geodetic bearings based on the Wisconsin North Zone Lambert Projection and have been transferred to the boundary lines within this project using a Wild North Seeking Gyro. All distances are geodetic grid distances.

This Survey was made by the U.S. Department of Agriculture, Forest Service, for the purpose of recovering, restoring, establishing, marking and perpetuating the corners and boundary lines of U.S. Government Land on the sections within this project area.

The Original Government Survey of this township was made in 1865 by William E. Daugherty.

The field notes of this survey and a copy of this and the remaining sections in this project area are on file in the Forest Supervisor's Office at Rhinelander, Wisconsin, and the District Ranger's Office at Florence, Wisconsin.

CORNERS RECOVERED AND RESTORED1. Northeast Section Corner.

Corner position restored from recovered original bearing tree evidence

Corner references recovered:

Tamarack (stump)	20"	N69°E	17.16 feet
Birch (stump)	18"	S60°W	14.52 feet

New Corner references:

Maple	12"	N44°E	60.63 feet
Spruce	18"	N18°W	69.93 feet

2. East Quarter Corner.

Corner position restored from a recovered 4"x4" wood post and nearby location poster accepted as best available evidence.

Corner references:

Cherry	10"	S41°E	55.31 feet
W. Birch	10"	N03°W	59.94 feet
Steel sign post		Southeast	1.00 feet

3. Southeast Section Corner.

Corner position recovered as restored by William Cochrane in 1977 using a 6"x6" wood post and original bearing tree evidence.

The 1977 corner references were cut down for the air photo project.

New Corner references:

Cedar	10"	North	53.50 feet
Cedar	11"	S48°E	37.53 feet
Cedar	12"	S84°W	50.57 feet
Cedar	11"	N30°W	36.01 feet
Steel Sign post		Northeast	2.00 feet

Stock No. 26273

T39N R14E SECTION 9

page 3 of 5

4. South Quarter Corner.

Corner position restored at midpoint and on line between the Southwest and Southeast Section Corners.

Corner references:

High point on NE side of 10' high ledge rock outcropping 28'x36'	N10°E	267.62 feet
River Bank	East	40.00 feet
Steel sign post	South	1.00 feet

5. Southwest Section Corner.

Corner position recovered as restored by William Cochrane in 1976 using a 4"x4" wood post with two older post alongside.

Corner references recovered:

Cedar	12"	S48°E	62.18 feet
Maple	8"	N51°W	22.76 feet

New Corner references:

Aspen	4"	S05°W	36.81 feet
Maple	8"	N73°E	48.51 feet
Steel sign post		Northwest	0.50 feet

6. West Quarter Corner.

Corner position recovered as restored by William Cochrane in 1976 using proportionate measurements.

The 1977 corner references were cut down for the air photo project.

New Corner references:

Maple	8"	N57°W	70.76 feet
Maple	12"	S36°W	67.65 feet
Steel sign post		East	0.30 feet

7. Northwest Section Corner.

Corner position recovered as restored by Bill Cochrane in 1976 from recovered 6"x6" scribed wood post and bearing trees by unknown surveyor as late as 1934.

The 1976 corner references recovered were cut down for the air photo project.

New Corner references:

Ash	5"	N12°E	41.71 feet
Ash	6"	S07°E	45.04 feet
Ash	5"	N86°W	41.06 feet
Ash	5"	N75°E	42.09 feet
Steel sign post		Northwest	2.00 feet

8. North Quarter Corner.

Corner position restored from a recovered 6"x6" wood post and nearby 16" cedar with location tag accepted as best available evidence of the corner position.

Corner references:

W. Birch	9"	S38°W	47.16 feet
Cedar	12"	N49°W	67.60 feet
Steel sign post		Northwest	1.00 feet

Stock No. 26273

T39N R14E SECTION 9

page 4 of 5

CORNERS ESTABLISHED1. Northwest Sixteenth Corner.

Corner position established at the intersection of straight lines between opposing sixteenth corner positions on the perimeter of the northwest quarter of the section.

Corner references:

S. Maple	6"	S62°E	12.68 feet
S. Maple	7"	South	12.52 feet
Steel sign post		N45°E	1.02 feet

2. Center-West Sixteenth Corner.

Corner position established at midpoint and on line between the West Quarter Corner and the Center-Quarter Corner.

Note: Corner falls on Northeast corner of a large rock. Marked with an X.

Corner references:

Ash	9"	N72°W	12.48 feet
Ash	8"	N11°W	12.13 feet
Aluminum Mon.	1"	S87°58'15"W	4.60 feet

3. North Sixteenth Corner between sections 8 and 9.

Corner position established at mid point and on line between the West quarter Corner and the Northwest Section Corner.

Corner references:

B. Spruce	5"	S49°W	52.31 feet
Balsam	7"	N46°W	57.04 feet
Steel sign post		N20°E	0.94 feet

Stock No. 26273

T39N R14E SECTION 9

page 5 of 5

SURVEYOR'S AFFIDAVIT

State of Wisconsin)
County of Forest) ss

I, William B. Cochrane, Land Surveyor, U.S.D.A. Forest Service, and a Registered Land Surveyor in the State of Wisconsin, hereby certify that I have surveyed and sub-divided Section 9, Township 39 North, Range 14 East, Fourth Principal Meridian, State of Wisconsin.

The plat map and survey notes herewith are a correct representation of the land surveyed and sub-divided. I have surveyed and sub-divided said section in accordance with the rules for the Survey of Public Lands and the Statutes of the State of Wisconsin.



William B. Cochrane
Land Surveyor, U.S.D.A. Forest Service
R.L.S. State of Wisconsin
Certificate #S-1107

SURVEYOR'S AFFIDAVIT

State of Wisconsin)
County of Forest) ss

I, Gary L. Pisoni, Contract Land Surveyor for the U.S.D.A. Forest Service, and a Registered Land Surveyor in the State of Wisconsin, hereby certify that I have surveyed the boundary lines and monumented the Sixteenth Corners of Section 9, Township 39 North, Range 14 East, Fourth Principal Meridian, State of Wisconsin.

I have surveyed and monumented said Section in accordance with the rules for the Survey of Public Lands, the Statutes of the State of Wisconsin and the subdivision field notes computed by William B. Cochrane, Land Surveyor, U.S.D.A. Forest Service.

Gary L. Pisoni
Land Surveyor
R.L.S. State of Wisconsin
Certificate #S-1634

Survey requested by: Edward [Signature] 3-22-89

District Ranger

Date

Date of Survey: 1988

