



4331229 0000 2025

☐ Check here if additional information is shown on the reverse side of this form.

The original corner was established in 1865 by James Nowlin. Original bearing trees: birch, 20", N40W, 70 links and a sugar, 10", N40E, 25 links. In the 1930's resurvey of part of this township, this corner was described as: "Found bluish grey stone with a cross on top in centerline of road and North edge of old RR. grade. B.T. all gone Set W.C. 50 links E and marked stone N73W, 46.4 links and stone N46E, 74.3 links. An undated map filed as record number 30573, is a survey of lots in the NE quarter of Section 32 by Gary Radtke. Said map shows a pipe 33 feet west of the section corner. On Feb. 27, 2025 I found an iron pipe about 4" below road surface in Hwy "S". The distance to the pipe west (which is leaning a bit to the west) works very well with what Radtke shows on map 30573. I accept the location of the iron pipe found as the best evidence of the original corner. The 1930's witness stones appear to have been covered or destroyed when CTH "S" was rebuilt. I topped the existing iron pipe with a gear headed spike and measured ties as shown below.

For the corner, I left the iron pipe in place and topped it with a gear headed spike.

A diagram of a compass rose. It consists of a circle with a vertical line passing through its center. The word "NORTH" is written vertically along the right side of the circle. The word "SOUTH" is written vertically along the left side of the circle. The word "EAST" is written horizontally along the top of the circle. The word "WEST" is written horizontally along the bottom of the circle.

