4.877

• • • • • • • • • • • • • • • • • • • •	CERTIFIED LAND CORNER RESTORATION
State of Wisconsin	
County of Forest	SS.
I found evidence of the	k do hereby certify that on the 26 day of July 19.73, east quarter corner of section 6. Range 16 east Fourth Principal Meridian, as described idence I established a new monument and accessories as described hereon to perthis corner:
Description of original monume	ent and accessories and subsequent restorations:
Survey in 1858 by James I set post. Tam. 7 inches, bears S78 W. Pine 8 inches, bears I	McBride 38.10 chains South corrected between sections 5 and 6 or 21 lks. N71 W 13 lks.
Description of corner evidence	found:
1. Old post point 2. W. Pine snag scribed, 3. Tamarack stump scribe	
Replaced old post point with filled with concrete with	accessories I established to perpetuate the location of this corner: with 2 inch inside diameter galvanized pipe 5 feet long a brass cap marked T34N, R16E, 1/4, S6, S5, 1974, S-802 owing new bearingstrees bear
Cedar 5 inches bears Cedar 12 inches bear Steel post 1.0 N. E.	s S21°E 11.68 ft. rs N31°W 11.30 ft.
	RHINELANDER, WIS. RHINELANDER, WIS. RHINELANDER, WIS. RHINELANDER, WIS. RHINELANDER, WIS.
	Resident witnesses
Sec. 6	Dated at Rhinelander Wisconsin, this 2/ day of Feb. 1974 Signature Jean F. Resvick Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-802 DOCUMENT No. 105089
	Office of Register of Deeds County of FGREST I hereby certify that the within instrument was filed in this office for record
Corner monument restore	on the 5th day of April 19.74, and was filed in Book No. Page No. of County Records.
m34 North · n-	Signature Cugenet States of Title Register of Deeds