

## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin

County of Forest

ss.

I Jean F. Resvick, do hereby certify that on the 25th day of June, 1969, I found evidence of the South Quarter corner of Section 35 Township 35 North, Range 15 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

## Description of original monument and accessories and subsequent restorations:

Surveyed in 1859 by James McBride. 40.00 chains West between Sections 2 and 35 set wood post.

Sugar 12 in. N10E, 37 lks.

Sugar 12 in. S10E, 40 lks.

A stream, 8 lks. wide, running NE bears west 18.55 chains.

A stream 6 lks. wide, running south, bears east 3.10 chains.

Enter Alder bottom, 2.50 chains East, bears North and South

Leave Alder bottom 6.50 chains east of post.

## Description of corner evidence found:

A squared post 1.47 chains West of Alder Bottom from post West to stream measures 18.5 chains. From post East to stream measures 3.23 chains. From post east 6.67 chains leave Alder bottom. By evidence of natural calls to post found is accepted as being the true position of the corner. The post has been in place for 40 years plus. Signs of older post were found along side said post.

## Description of monument and accessories I established to perpetuate the original location of this corner:



Replaced post with 2 inch inside diameter galvanized wrought iron pipe 5 feet long, filled with concrete with brass cap marked:

From which the following new blazed and scribed bearing trees bear:

Maple 13 inch. diameter bears S86E, 17.19 feet or 26.04 lks.


Maple 14 inch diameter bears N3W, 20.19 feet or 30.59 lks.

4 x 4 cedar post bears North 1.4 feet or 2.12 lks.



● = Corner monument restored

□ =



Resident witnesses

Dated at Rhinelander

Wisconsin, this 22nd day of

1969.

Signature Jean F. Resvick

Title Cadastral Surveyor

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S-802

DOCUMENT No. 98040

Office of Register of Deeds

County of Forest

I hereby certify that the within instrument was filed in this office for record on the 22nd day of May, 1970, and was filed in Book No. Page No. Z-19 of County Records.

Signature Eugene Stutz

Title Register of Deeds

Township 35 North, Range 15 East

Section 35

Index No. Z-19

Page No.

42515350020

719

U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS: This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.  
○ = Corner monument restored.


Quarter corner common to Sections 2 and 35,  
T34-35N, R15E, Forest County, Wisconsin.

REGISTER'S OFFICE  
Forest County, Wis.

Received for record this 19th day  
of December A.D., 1988 at

2:50 o'clock P.M. and recorded  
in Vol. CORNER RESTORATIONS  
page A-19

*Paul Aschenbrenner*  
Register of Deeds



- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

In 1857, A Curtis set a wood post for the corner and the following corner references:  
Sugar 12" N10°E 37 lks. Sugar 12" S10°E 40 lks.


In 1969, Jean Resvick found the wood post. Replaced post with 2" inside  
dia. galvanized iron pipe with brass cap stamped to identify the corner. Corner references:  
Maple 13" S86°E 17.19 ft. Maple 14" N3°W 20.19 ft. 4"X4" cedar post North 1.4 ft.

In 1988, John Schulke the corner as described on the Corner certificate Document #98040  
done by Resvick. Found the following corner references: Sugar Maple 19" N01°W 17.56 ft.  
Sugar Maple 18" S88°E 20.24 ft. Rotten wood Post North 1.5 ft.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)  
Describe witness monuments.

- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

- 2" inside dia. galvanized iron pipe with a brass tablet stamped to identify the corner.
- Sugar Maple 19" N01°W 17.56 feet
- Sugar Maple 18" S88°E 20.24 feet
- Red Maple 10" N46°E 38.47 feet
- Sugar Maple 9" S64°W 25.39 feet
- Steel sign post West 1.3 feet



- (e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

No discrepancy.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2) found perpetuated location.

- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

- (1) I, John Schulke  
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

Date

Certificate ready for filing:

Dale B. Stacey  
District Ranger

