CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	
State of Wisconsin County of Forest State of Wisconsin State of	•
Township35. North	, do hereby certify that on the
Description of original monument	and accessories and subsequent restorations:
Surveyed by James McBride Set Post for Section Corner Birch 24", N84°E, 27 lks. Elm 15", S48°E, 36 lks. Sugar 8", S10°W, 15 lks. Sugar 10", N86°W, 26 lks.	er.
Description of corner evidence fou	ınd:
Mound of stone with post 1 Decayed sugar stump, N86° Stump hole, N84°E, 27 lks. Stump hole, S48°E, 36 lks. New Sugar BT's 12 - 15 years.	W, 26 lks. •
	essories I established to perpetuate the location of this corner:
concrete filled, with bras	ameter galvanized iron pipe 30 inch long in post hole, ss cap stamped: , S27, 1979, S-1558. Replaced mound of stone.
From which the following themlock 20", N24°E, 92.63" *Sugar Maple 10", S48°E, 7. Hemlock 18", S31°W, 22.28" *Sugar Maple 10", N82°W, 6. Steel sign post, N45°W, 1. *BT's scribed 12 - 15 year	DOCUMENT NO. DOCUMENT NO. STEFAN S-1558
	Resident witnesses
Sec. 27	Dated at Laona Wisconsin, this 3 day of November 19.80. Signature Milo E. Stefan Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. S-1558
	Office of Register of Deeds County of Forest
Corner monument restored	I hereby certify that the within instrument was filed in this office for record on the 2nd day of June 19.81, and was filed in Book No
35N D	Signature Lugini Section 27 Inde No. Re-17 Page No.

4351622 ddd

R 17