

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin

County of Forest

ss.

I Milo E. Stefan, do hereby certify that on the 5 day of September, 19 79,
I found evidence of the North East Section corner of Section 26
Township 35 North, Range 16 West, Fourth Principal Meridian, as described
hereon; and that from this evidence I established a new monument and accessories as described hereon to per-
petuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Surveyed by James McBride in August 1858.
Set Section Corner Post.
Fir 10", N21°E, 35 lks.
Sugar 7", S64°E, 28 lks.
Hemlock 10", S11°W, 19 lks.
Basswood 20", N61°W, 19 lks.

Description of corner evidence found:

6" X 4' cedar post with fallen old post along side.
Remains of large basswood in clump of young basswood
N60°W, 19 lks.

Description of monument and accessories I established to perpetuate the location of this corner:


Replaced cedar post with a 2 inch inside diameter galvanized iron pipe
36 inches long concrete filled with brass table stamped:
T35N, R16E, S23, S24, S25, S26, 1979, S-1558.

Placed mound of stone around monument.

From which the following bear:

Hemlock 20", S78°E, 63.46'
Sugar Maple 10", S3°E, 27.69'
Basswood 10", S64°W, 30.08'
Basswood 12", N10°W, 42.62'
Steel sign post, N60°E, 1.0'

DOCUMENT NO.
119860



● - Corner monument restored
□ -

Resident witnesses.....

Dated at Laona Wisconsin, this 3 day of November
19 80

Signature Milo E. Stefan Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. 1558

Office of Register of Deeds County of Forest

I hereby certify that the within instrument was filed in this office for record
on the 2nd day of June, 19 81 and was filed in Book
No. _____ Page No. _____ of County Records.

Signature Eugene J. Stetson Title Register of Deeds

Township 35N, Range 16E, Section 26, Index No. R-21, Page No. _____

43516230000

R21