State of Wisconsin

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. S-Z

11 N 1/16

History of original corner establishment:

Corner established by B. F. Dorr, County Surveyor, in 1899.

H. C. Lawrence, Registered Land Surveyor, recovered Dorr's old post and point in 1954.

Set new post, 3" tamarack and marked NBTs, Black Spruce 6" N 58° W 21½ 1ks and

Black Spruce 4" S 88° E 56½ 1ks.

Description of corner evidence found:

Recovered Lawrence's 3" tamarack post, squared and scribed S 25 N 1/16, S 30 in fair condition.

Recovered OBT Black Spruce 6" N 58° W 21.5 lks (24 lks) Scribed S 25 BT.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced 3" tamarack post with 1" OD iron pipe with 2" brass cap, stamped.

Pipe projects 18" above ground.

NBT - Black Spruce 6" S 61° W 32 lks, scribed 1/16 BT.

S498

Pipe and BTs painted blue.

R

Dated at Rhinelander	Wis., this	23 rd	day of	Marc	h	, 19.76
Signature Millip J. J. M. M. (County Surveyor, Registered			•			n No. S-498
(County Surveyor, Registered	Land Surveyo	or, or other du	ly authorized offic	ial)		• ·
Office of Register of Deeds, County of instrument was filed in this office for recon	rd on the	31st	day of	March	eby certify	tnat the within 19.76
at 3:30 o'clock P. M. Lugene With Takense	_	* -		OCU MENT		108952