JEDTIELED.	1 4 4 1		RESTORATIO	. A. I
.PRHFIFI	LIVIA	LURINER	RESIDRATIO	HV
<i>_</i>		COILLE		

Index No.

CPI-1976

History of original corner establishment:

Corner established by Charles Walker, County Surveyor.

No records of survey or BT's established.

Description of corner evidence found:

Recovered pieces of old post and the old point well preserved in muck and moss. This was a squared cedar post.

Unable to recover any evidence of any BT's.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced point of old cedar post with limit iron pipe with 2" brass cap, stamped.

Monument projects 24" above ground.

NBT's - Tamarack 6" North 11.6 links, scribed 1/16 BT.

Tamarack 8" S 54° E 62.2 links, scribed 1/16 BT.

Monument and BT's painted blue.

Replaced point of old cedar post with line iron pipe with 2" brass cap, stamped.

S498

Tamarack 8" S 54° E 62.2 links, scribed 1/16 BT.

Replaced point of old cedar post with line iron pipe with 2" brass cap, stamped.

S498

Tamarack 8" S 54° E 62.2 links, scribed 1/16 BT.

Replaced point of old cedar post with line iron pipe with 2" brass cap, stamped.

S498

Tamarack 8" S 54° E 62.2 links, scribed 1/16 BT.

Replaced point of old cedar post with line iron pipe with 2" brass cap, stamped.

Dated at Rhinelander	, Wis., this	31st	day	of	August	. 19.76
Signature hill Lange County Surveyor, Registered Office of Register of Deeds, County of	Title	Registered	Land	Surveyor	Registration	No. S-498
(County Surveyor, Registered	d Land Survey	or, or other duly	y author	ized official)		
Office of Register of Deeds, County of instrument was filed in this office for reco	Fore	est 8th	<u>}</u>	day of	I hereby certify to September	hat the within 19.76
at. 16 o'clock M. Care State (Register of Deeds)	M	~~~~~~~~~~			DOCUM	ENT NUMBER
(Register of Deeds) By		Deputy	•			