O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Original corner established by Wm. E. Dougherty, Deputy Surveyor, in 1859, from which Birch 12" bears S50°E 29 lks. and Hemlock 10" bears N61 W 26 lks. Line between Sec. 29 and 32, ran by I.R. Ritter, County Surveyor in 1931.

Description of corner evidence found:

Recovered I.R. Ritters 1/4 Corner between Sec. 29 and 32, $1\frac{1}{2}$ " x 3' iron pipe and his Sugar Maple 12" S54°W 7 lks. Ran random line S86°E from 174 Corner, distance of 42.38 chains to point 2.522 chains south at right angles, to interesection of centerline of Tower Road and Ison Road. True computed distance of line 42.45 chains. Corrected bearing S89° 24' E.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 13" x 18" iron pipe at the intersection of Tower Road and Ison Road, 4" below surface. Set a 25" Berntsen A-1 Federal Monument for Witness Corner 55 lks. West.

Pipe projects 18" above ground. Cap stamped. NBTs - Sugar 6" S36°W 147 lks., scribed SC BT.

N69°W 119.7 lks., scribed SC BT. Sugar 6" S31 E 131 lks, scribed SC BT.

Measurements and bearings made to true corner. Pipe and BTs painted blue.

R12E T36N E 55 lks to Cor.

, Wis., this 21st day of June (Jounty Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest 1. I hereby certify that the within instrument was filed in this office for record on the 22nd day of June 19.76... at 3=45 o'clock Pa Mn