O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. Z-6

History of original corner establishment:

By Celeur Schmidt

Description of corner evidence found: Searched for, but found no evidence of any corner present. Established corner by proportion measurement between Section Corner 32-33, 5 and 4, and Section Corner 31, 32, 5 and 6. Ran traverse between two established corners, total distance 79.907 chains, bearing S 89° 08' 55" W.

Upon setting the corner, made an additional search of the area, but no evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner. Set $1\frac{1}{2}$ " iron pipe with 2" brass cap for corner. Cap stamped. Pipe projects 2' above ground.

NBTs - Sugar Maple 8" S 27° W 25.1 lks, scribed 1/16 BT.

Sugar Maple 7" S 81° W 4.1 lks, scribed 1/16 BT.

Pipe and BTs painted blue.

S498

T36N R12E

W 1/16 $\frac{S}{S}$ | 32

CPI - 1976

Dated at Rhinelander	, Wis., this	30th	day	y of	June	. 1976	
Signature Thilip Tannon! County Surveyor, Register Office of Register of Deeds County of	Title Re	gistered	Land	Surveyor	Registrat	ion No. 5-498	
(County Surveyor, Register Office of Register of Deeds County of	ed Land Surveyo Forest	r, or other di	ily autho	rized official)	I hereby certi	fy that the withi	
instrument was filed in this office for rec	ord on the	23rd		day of	July	19 76	
at 3:00 o'clock P. M.				DOCUMENT NUMBER			
EUGENE STATEZNY			-		109	252	
(Register of Deeds)							