O = Corner monument restored.

CERTIFIED	LAND	CORNER	RESTORATION

History of original corner establishment:

Original subdivision by James L. Nowlin June 2 - June 12th 1865

S60W N30E 30 Lks 35 Lks Eindock Hemlock

Description of corner evidence found:

2" iron pipe found 5' long with brass cap set by C.E. Walker in 1938


Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Ties:

N16W S75E Ash

16.90 feet 17.55 feet



	ckA.M.	11			cumont.	Mamban	108047
nstrument was	filed in this office for rece	ord on the	27t1	1day	of0	ctober	, 19 .7.5
Office of Registe	er of Deeds, County of		Forest	• •	-	I hereby ce	rtify that the within
	(County Surveyor, Registere	ed Land Surv	eyor, or ot	her duly authorized	official)	_	
Signature. L. he	mas R. Dunet	Title	Land	Surveyor		Regists	ration No. S <u>-887</u>
Dated at	Crandon	.,Wis., this.	23rd	day of	Octo	ber	, 19.75