O = Corner monument restored.

State of Wisconsin

Thomas R. Arnott ,, do hereby

certify that on the 19th day

of January 19.76, I found

evidence of the section

corner of sections 19, 24, 25 & 30

County of Forest

SS.

CERTIFIED LAND CORNER RESTORATION

Index No.

History of original corner establishment:

Hemlock	12	N4OE	7 Lks.
Ironwood	8	M48W	27 Lks.
Ironwood	8_	S58W	28 Lks:
Hemlock	8	S25E	31 Lks.

Description of corner evidence found:

2" iron pipe 5' long with bræss cap set by C.E. Walker in 1938

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Ties:

[aple:	8	N34W
Hemlonk	16	S27E
Hemlock	14	S43W

37.62 feet 36.30 feet 35.05 feet

ARNOTT S-887
WIS. SURVENIENTERS OF THE SURVENIENTER

Dated at Crandon	, Wis., this 26th	day of January	
Signature / Nozami Alana (County Surveyor, Registered	Title Surveyor. d Land Surveyor, or other duly a	Regists uthorized official)	ration No.S887
Office of Register of Deeds, County of	Forest	, I hereby ce	rtify that the withi
instrument was filed in this office for recordated in the source of the	rd on the 20でい	day of January	, 19 <i>[</i> .
			4

(Register of Deeds)

Document Number

Depu