O = Corner monument restored.

CERTIFIED	LAND	CORNER	RESTORATION	٠,
		COMILIA	NESIGNATION	•

Index No.

History of original corner establishment: Original corner established by James McBride, Deputy Surveyor, in 1859 from which cedar 12" bears N37°W, 26 links, cedar 14" bears N10°E, cedar 8" bears S52°E, 11 links, and hemlock 5" bears S18°W, 16 links.

No record of any subsequent surveys.

Corner recovered and maintained by Consolidated Papers Foresters since 1940.

Description of corner evidence found:

Recovered 4" cedar post squared and scribed S9,S10, S15,S16 in poor condition. Also recovered a 1-1/2" iron pipe setting beside wooden post.

Recovered OBT cedar 14" N38 W 24 links scribing partly visible, now dead and fallen down.

Cedar 12" S58°E 37 links scribed Sec. Cor. BT Hemlock 12" S76°W 21 links scribed Sec. Cor. BT

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced wooden post and iron pipe with 2-1/2" Berntsen, A-1 Federal Monument, aluminum with magnet installed in cap and base. Pipe projects 18" above ground. Old post and iron pipe set up beside new pipe. Cap stamped -

NBT - Cedar 7" N20°E 40.3 links faced but not scribed

S9 S10

Pipe, post, and BT's painted blue.

T36N R14E

S9 S10

S16 S15

Dated at	Argonne	, Wis., this	5th	day of	January	<u>, 1976</u> .
	County Surveyor, Regis			<del>-</del>		
Office of Registinstrument was	ter of Deeds, County o s filed in this office for a	ecord on the	Forest 4th	dav of	I hereby certify February	that the within
at 4:00 o'cl	ockP. M.				T NUMBER	108709
Luge	ne States (Register of De	eds)				

y......Deput