145201

State of Wi	sco	nsin]
County of FOR	ES	Γ	ss.
I Glen Barker certify that on the of January ablished the Sectorner of	Juar ion For and mo	th, 19. ter Section 1 & 12 orth Principle that from nument a	, do hereby day 91, I est- n North, Range pal Meridian, this evidence nd accessories
Posidont witnesses			
Resident witnesses: N. Spiess		•	
			~~
J. Spiess			
T361	N _	R15E	
	1	1/4	1
] 1		[
	-		·
į.	1		1
\ \	s i	12	†
 	-	-	<u> </u>
L	i [
1	 1		1
	ا ا		
ļ .			1
 	1		
O = Corner monume	ent	restored.	

CERTIFIED LAND CORNER RESTORATION U.S. PUBLIC LAND SURVEY

Index No.E-23

T36N R15E

FOREST COUNTY

History of original corner establishment:

Original comer established by A. Curtis, Deputy Surveyor in 1858 from which 10" Fir bears N36W, 11 lks. and Aspen bears S48E, 10 lks.

Description of corner evidence found:

Re-established Quarter Section Comer by proportional measurement. Total distance from previous northwest and northeast Section Comer of Section 12 is 5221.22'. Set Quarter Section Comer 2610.61' intermediate.

No evidence of original or other corner or accessories. Corner position sets on north edge of old clearing. Tested original call west of re-established corner to swamp 3.25 chs. Distance very good.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2 - 1/4" Aluminum Forest County Monument with 3 - 1/4" alloy cap. Monument projects 7" above ground.

By......Deputy

MARKED N.B.T.'s: N3 30,E Sugar 68.14' S89E 19.20' Sugar White Spruce S24E 34.36' 1992 White Spruce 35.67' S1682

Dated at	Rhinelander		24th	day of	April		. 19	92
Signature	Dow Daylar	Title	-	Land Surve	<u>-</u>	Registration No	S-16	82
		Registered Land Survey		ly authorized o	official)	O -		
Office of Renstrument	egister of Deeds, Cour was filed in this office	nty of	- 34	day (of	I hereby certify that the complete of the comp	the w	ithi 92
t 9:30	oʻqlock	[.						
	faul Asc	len6 kennes						
	(Register	of Deeds)		- -				

Describe any material discrepancy between the location of the corner as restored reestablished and the location of that corner as previously restored or reestable by distance and direction. Show the discrepancy on the plan view drawing under above. Show the distances between the corner as previously restored or reestable and (1) the corner as restored or reestablished, and (2) to at least 2 of the monuments shown on the drawing in (d), above.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location?
- {g&h} Was the corner reestablished through lost corner proportionate methods? If sq. the method, including the directions and distances to other public land survey communities as evidence or used for proportioning in determining the corner location?

Proportionate method

(i)

T 36 N 1 6 12 7

1 0 N89° 52'13"E 2 2610.61' Re

Re-established 2610.6

RISE RIGE

1/4 Cor.

Glen Barker

[type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct/and complete to the best of my knowledge and belief.

Signature Dat

Affix Exercise Scal

GLEN

BARKER

S-1682

CHANDON

WI